FEDERAL BUREAU OF INVESTIGATION FOI/PA
DELETED PAGE INFORMATION SHEET FOI/PA# 1341051-1

Total Deleted Page(s) = 6
Page 21 ~ Referral/Direct;
Page 54 ~ Duplicate;
Page 55 ~ Duplicate;
Page 56 ~ Duplicate;
Page 143 ~ Referral/Direct;
Page 144 ~ Referral/Direct;

GENERAL INVESTIGATIVE DIVISION

This concerns the 12/1/72, crash of United Airlines (UAL) Flight 553 at Chicago, Illinois.

Attached relates that the Federal Aviation Administration has indicated no possibility of any cause of crash other than pilot error. According to witnesses, UAL Flight 553 stalled and thereafter crashed during maneuver to pull out of final approach because it got too close to a small private aircraft which was preceding it. Total of 45 dead (including 2 who were on the ground) with 18 survivors. Liaison being maintained with the National Transportation Safety Board.

No further active FBI investigation being conducted in view of no apparent Destruction of Aircraft or Motor Vehicle violation. FBI Disaster Squad is on scene attempting to identify podies.

DGF:pdh

FEDERAL BUREAU OF INVESTIGATION COMMUNICATIONS SECTION

DEC 001972

TELETYPE

NRØ19 CG PLAIN

826PM URGENT 12-8-72 RWR

TO ACTING DIRECTOR

ALEXANDRIA

WFO

OMAHA

FROM CHICAGO (149-NEW)

3P

CRASH OF UNITED AIRLINES FLIGHT FIVE FIVE THREE.

A BOEING SEVEN THREE SEVEN, AT CHICAGO, ILLINOIS, DECEMBER
Destruction of Aircraft or Motor Vehicles
EIGHT, SEVENTYTWO. BANV.

Reference
AE CHICAGO TELEPHONE CALLS TO THE BUREAU AND ALEXANDRIA,
AND WFO, INSTANT.

CAPTIONED PLANE, A BOEING SEVEN THREE SEVEN, CRASHED AT

SEVENTIETH AND LAWNDALE AVENUE, CHICAGO, ILLINOIS, AT

APPROXIMATELY TWO TWENTYONE PM THIS DATE. THE PLANE

Central Standard Time

DEPARTED WASHINGTON, D.C., AT TWELVE FORTY PM CST AND WAS

SCHEDULED TO ARRIVE AT MIDWAY AIRPORT, CHICAGO, ILLINOIS,

AT TWO THIRTYONE PM CST. THERE WERE FIFTYTWO PASSENGERS

AND A CREW OF SIX WHICH INCLUDED THREE STEWARDESSES AND THREE

FLIGHT OFFICERS.

DEC 11 1972

THIRTEEN PASSENGERS AND TWO STEWARDESSES ARE ALIVE AND HAVE BEEN IDENTIFIED.

END PAGE ONE

₹ ODEC 19 1972

b6 b7C

Mr. Felt

Mr. Baker

Mr. Callahan

Mr. Cleveland

Mr. Conrad

Mr. Dalbe

Mr. Jenk

Mr. Marsha

Mr. Miller Mr. Purvis Mr. Soyars

Mr. Walters Tele. Room

Mr. Kinley
Mr. Armstrong
Ms. Herwig

Mrs. Neenan .

Mr. Gebhard

13

6/14/1

PAGE TWO

THE PLANE CRASHED INTO SEVERAL SINGLE FAMILY

DWELLINGS. THE NUMBER OF INJURIES AND FATALITIES TO

PERSONS IN THE CRASH AREA IS NOT KNOWN AT THIS TIME. THERE

WERE SEVERAL FIRES TRIGGERED BY CRASH.

SUPERINTENDENT JAMES CONLISK, CHICAGO, ILLINOIS, PEX AND

United Airlines

CAPTAIN

EXECUTIVE, UAL, ELK GROVE VILLAGE,

ILLINOIS. HAVE REQUESTED THE SERVICE OF THE FBI DISASTER UNIT.

A PLAYBACK OF THE RECORDING TAPE AT MIDWAY AIRPORT INDICATES POSSIBLE PILOT ERROR. ACCORDING TO THE TAPE AS FLIGHT FIVE FIVE THREE APPROACHED RUNWAY, A SMALL AIRCRAFT WAS ALREADY ON THE RUNWAY, THE PILOT OF FLIGHT FIVE FIVE THREE WAS INSTRUCTED TO MAKE A LEFT TURN AND COME TO A HEADING OF ONE EIGHTY DEGREES. THE PILOT ACKNOWLEDGED THE TRANSMISSION AND THE PLANE DISAPPEARED FROM RADAR. THE TAPE THEN INDICATES A FLUTTERING SOUND WHICH MIGHT HAVE COME FROM THE STALL SPEED INDICATOR, INDICATING THE PILOT HAD LOST HIS SPEED AND CRASHED.

TWO STEWARDESSES AND A FEDERAL NARCOTICS AGENT WHO WERE Bureau Agents
ABOARD THIS PLANE HAVE BEEN INTERVIEWED BY BUAGENTS AND THEY
END PAGE TWO

b6 b7C PAGE THREE

STATE NOTHING UNUSUAL HAPPENED PRIOR TO CRASH.

COMPLETE PASSENGER MANIFEST OBTAIN FROM UAL WITH CONTACT POINTS FOR ALL PASSENGERS.

Chicago Police Department CLOSE LIAISON BEING MAINTAINED WITH CFB AND

NATIONAL TRANSPORTATION SAFETY BOARD.

U.S. CONGRESSMAN GEORGE COLLINS, CHICAGO, ILLINOIS,
HAS BEEN MANIFESTED ABOARD THIS FLIGHT ACCORDING TO UAL RECORDS.
NO OTHER INFORMATION CONCERNING COLLINS AT THIS TIME.

ASAC, CHICAGO, ON SCENE AND HANDLING INVESTIGATION PERSONALLY.

INFORMATION COPY TO OMAHA AS FLIGHT FIVE THREE WAS TO TERMINATE OMAHA.

END

HOLD

cc: Room 5634

FEDERAL BUREAU OF INVESTIGATION
COMMUNICATIONS SECTION

DEC 091972

TELETYPE

NRØØ1 CG PKAIN

320 AM URGENT 12-9-72 MFM

TO ACTING DIRECTOR

FROM CHICAGO (149-NEW) 1P

CRASH OF <u>UNITED AIRLINES</u> FLIGHT FIVE FIVE THREE, A BOEING SEVEN THREE SEVEN, AT CHICAGO, ILLINOIS, DECEMBER EIGHT, SEVENTYTWO. DAMV.

RE BUCALL TWELVE EIGHT LAST AND CG TEL TO BUREAU TWELVE EIGHT LAST.

ON SCENE INVESTIGATION INDICATES PILOT ERROR AS CAUSE OF CRASH.

NO INFORMATION RECEIVED OR DEVELOPED BY CHICAGO
TO INDICATE CAUSE OF CRASH DUE TO SABOTAGE.

THREE VICTIMS, ON BOARD AIRCRAFT, INTERVIEWED. NO INDICATION OF SABOTAGE OR SKYJACKING.

REVIEW OF TAPED CONVERSATIONS BETWEEN PILOT AND TOWER DETERMINED STALL INDICATOR ACTIVATED JUST PRIOR TO CRASH, DENOTING FLIGHT SPEED INSUFFICIENT AT TIME PILOT RECEIVED LANDING WAVE OFF.

INVESTIGATION CONTINUING. BUREAU WILL BE KEPT ADVISED.

E ND

259

TMT FBI SOG PODEC 9 1972

Mr. Feit Mr. Baker -Mr. Callahan Mr. Cleveland Mr. Conrad Mr. Dalbey Mr. Gebhardt Mr. Jenkins Mr. Marshall Mr. Miller, E.S. Mr. Purvis . Mr. Soyars . Mr. Walters . Tele. Room . Mr. Kinley . Mr. Armstrong . Ms. hervat . Mrs. Neenat

1

10024 - 2

22 DEC 11 1972

6-N/H

FEDERAL BUREAU OF INVESTIGATION

COMMUNICATIONS SECTION

DFC 0919

NRØØ2 CG PLAIN

2:34PM:12/9-72 URGENT KMD

TO ACTING DIRECTOR

FROM CHICAGO (149-NEW) 3P

CRASH OF UNITED AIR LINES FLIGHT FIVE FIVE

BOEING SEVEN THREE SEVEN, CHICAGO, ILLINOIS, DECEMBER DESTRUCTION OF AIRCRAPT OR MOTOR VEHICLES

REFERENCE TELETUPE

RE CHICAGO LEL DECEMBER EIGHT LAST.

NEIGHBORHOOD INVESTIGATION IN VICINITY OF AREA OF CRASH OF UAL FLIGHT FIVE FIVE THREE REFLECTS INFORMATION FROM WITNESSES TO EFFECT THAT AIRPLANE WAS UNDER OBSERVATION UNTIL IT DISAPPEARED AND CRASHED. WITNESSES STATED THERE WAS NO EXPLOSION OR APPARENT DAMAGE TO AIRCRAFT BEFORE CRASH AND IT APPEARED TO BE MUSHROOMING INTO THE

THE TAIL WAS DOWN. NOSE ELEVATED ABOUT FORTY-FIVE DEGRE HOUSES.

AND UNABLE TO GAIN ALTITUDE.

FEDERAL AVIATION ADMINISTRATION INFORMATION FROM EAA REFLECTS NOPOSSIBILITY OF ANY

CAUSE OF CRASH OTHER THAN PILOT ERROR. ACCORDING TO CONSENSUS

OF INFORMATION FROM WITNESSES AND TOWER AT MIDWAY AIRPORT.

对扩张: 有规则

END PAGE ONE 7 ODEC 2 0 1972

Mr. Callanan Mr Cleveland Mr. Conred Wr. Dalue

r. Marchall Mr. Miller, E.S.

ir. Purvis . Mr. Sovers -Mr. Walters -

Tele. Room -Mr. Kinley .. Mr. Armstrong Ms. Fierwic

Me enar

b6

20 DEC 14 1972

b7C

PAGE TWO

THE FOLLOWING IS WHAT OCCURRED LEADING UP TO CRASH OF UAL FLIGHT FIVE FIVE THREE:

LANDING AT MIDWAY AIRPORT FOLLOWING A SMALL PRIVATE
AIRCRAFT. TOWER OBSERVED THAT DISTANCE BETWEEN FIVE FIVE
THREE AND PRIVATE AIRCRAFT WAS BECOMING MARGINAL. FIVE
FIVE THREE WAS ORDERED TO PULL OFF FROM APPROACH TURNING
LEFT TO A HEADING OF ONE HUNDRED EIGHTY DEGREES. THE PILOT
APPARENTLY THREW FULL THROTTLE TO THE ENGINES AND STARTED
TO TURN TO THE LEFT AT THE SAME TIME, PULLING UP THE NOSE OF
THE AIRCRAFT. THIS MANEUVER APPARENTLY CAUSED THE AIRCRAFT TO STALL
AND MUSHROOM INTO THE GROUND.

PERSONS INTERVIEWED INCLUDING FOUR SURVIVORS OF THE CRASH AND FAA INVESTIGATORS, IN ADDITION TO NEIGHBORHOOD WITNESSES, DEVELOPED NOTHING WHICH WOULD INDICATE ANY REASON TO BELIEVE THAT A VIOLATION OF THE DAMV STATUTE EXISTS. END PAGE TWO

PAGE THREE

DISASTER SQUAD HAS ARRIVED IN CHICAGO AND IT IS PRESENTLY AT COUNTY MORGUE IDENTIFIENG DEAD PASSENGERS. POSITIVELY IDENTIFIED ARE EIGHT BODIES. THERE ARE ONLY TWELVE BODIES WITH WHICH THE DISASTER SQUAD CAN WORK. THERE ARE FORTY FIVE BODIES AT THE MORGUE, THIS WOULD INCLUDE TWO PERSONS WHO WERE ON THE GROUND, WHO RESIDED IN NEIGHBORHOOD OF CRASH. THERE IS A TOTAL OF EIGHTEEN SURVIVORS.

FOR INFORMATION OF THE BUREAU, NATIONAL TRANSPORTATION

SAFETY BOARD (NTSB) SURVEYING CRASE SCENE. ENTIRE AREA EXTENSEVILY

PHOTOGRAPHED BY FBI AND SCENE DIAGRAMED. LIASION BEING

MAINTAINED WITH NTSB.

UACB, NO FURTHER INVESTIGATION BEING CONDUCTED OTHER
THAN TO ASSIST DISASTER SQUAD IN IDENTIFYING BODIES.
END

DKS FBI WASHDC CLR

December 9, 1972

This is new Destruction of Aircraft or Motor Vehicles case wherein on 12/8/72, United Airlines Flight 553, en route to Chicago, Illinois, from Washington, D.C., crashed in Chicago at approximately 2:21 p.m. Aboard were 52 passengers and crew of six which included three stewardesses and three flight officers.

Thirteen passengers and two stewardesses alive and identified; number of injuries and fatalities in crash area not known at this time; playback of recording tape indicates possible pilot error.

Chicago Police Department (CGPD) and United Airlines have requested service of FBI Disaster Squad; same being afforded.

According to United Airlines, Congressman George Collins (Democrat - Illinois) has been manifested aboard this flight; no other information concerning Collins known at this time.

ASAC, Chicago on scene and handling investigation personally; close liaison with CGPD and National Transportation Safety Board being maintained.

feltodured 12/9/12

RJP:erg

FEDERAL BUREAU OF INVEST WASHINGTON, D. C. 20535

December 26, 1972 DATE:

Re: UNKNOWN SUBJECT;

TO: Mr. C. O. Miller UNITED AIRLINES BOEING 737; ACCIDENT INVESTIGATION

> **Dôcument** P&C

LFPS

Rådio Engineering

b6 b7C

Director

Bureau of Aviation Safety

National Transportation Safety Board

Department of Transportation

Washing, D. C. 20591

Invoice of Contents Crypt.-Trans. 0.1 K1 Picked up by Date Special Instructions: FBI File No. 149-10024 Mail Room: Show shipment date and registry number. Shipping Room: Show shipment date: bill of lading number: initial invoice; return to Section checked in block; after PC-J3624 MK initialing in block, invoice to be placed in administrative file.

REPORT of the



FEDERAL BUREAU OF INVESTIGATION WASHINGTON. D. C. 20535

To:	Mr.	C.	0.	Miller	

December 29. 1972

1 - Office, 7133

Director

Bureau of Aviation Safety National Transportation Safety Board Department of Transportation

Washington, D. C. 20591

Re:

UNKNOWN SUBJECT: UNITED AIRLINES BOEING 737: ACCIDENT INVESTIGATION

L. Patrick Gray, III Acting Director

YOUR NO.

Examination requested by: Addressee FBI FILE

LAB. NO.

PC-J3624 MK

Reference:

Letter 12/12/72

Examination requested:

Chemical Analyses

Specimens: Personally delivered by Investigator

12/12/72

b6

b7C

Cockpit voice recorder magazine

MAILED 25K1

Antifreeze

DEC2 9 19 Result of examination:

The quantity of material in the small spots inside the Q1 magazine was too limited for identification; however, these spots did not come from the same source as the Kl antifreeze nor the sealing wax found on the exterior of the magazine.

Specimens Ql and Kl are being retained by the Laboratory until called for by your representative.

Baker _ Bates

Bishop

Callahan.

Cleveland Conrad _

Dalbey .

Jenkins .

Marshall .

Miller, E.S.

Ponder _

Sovars Walters

Tele. Room Mr. Kinley

Mr. Armstrong _ Ms. Herwig ___

Mrs. Neenan __ MAIL ROOM ___

RWA: 1mh (4)

TELETYPE UNIT

MO JAN 5 1973





Laboratory Work Sheet

Re:	UNKNOWN	SUBJ	ECT:
-----	---------	------	------

UNITED AIRLINES BOEING 737;

ACCIDENT INVESTIGATION

Mr. C. O. Miller

Director

Bureau of Aviation Safety

National Transportation Safety Board

Examination requested by: Department of Transportation

Washington, D. C. 20591

Examination requested:

Chem Anal (Gen Chem)

Date received: 12/12 perdel

Result of Examination:

Examination by:

Lab.# PC-J3624 MK

Let. 12/12

b6 b7C

Per del by Investigator on 12/12/72	Per	del by	Investigator		on	12/12/72
-------------------------------------	-----	--------	--------------	--	----	----------

Q1

Cockpit voice recorder magazine

K1

Antifreeze

Loo of

PC- J3624 m/c K ~ 100ml total realed zer 1 H markers tope K, evaparated 25 mlK on hot plate (wouldn't jelly consistency material with solme (merthiolate") whores original soln I.R. of this jelly and K as is shows to be ["ethylene") glyens. gives hright yellow fluorerence under 4. V. light long & short smallert sport of the Videble grange matural even when dry still giver yellow fluorisende Millim mest - none Pries to leave definite colored most

The spirks, seem to follow the "tape path" observation under u. v. of q along with the first sport of t, shows the spec not to be from thek, since there is no yellow at on addition me witnes to eye at 60x of the mentholecte color. The prote as not the same or the realing way seem of of deagrand since the wax is Strongly colored and is hard. Most of the specks of que dry and without substance Thowever pome have a heavy liquid nature - lint the quantity is to limited (and maybe thick) to proke syl directly even anothe micro engle used for The.

Leighe's sput test for gly obs have limit of 5 y - in addition compliabled reagents for apatterts Their appears to be one or two spots of the same substance on the tape (would have come from laying over on the spats on the backlooks. Since yests seem to follow tage line looked under 20x + 4.4. in electronic area no port of liquiforend.

Tried to pick up spots volleatively with oninmum quambite of extels for T.R. - No hint of spectrum w brann condinser

Spectro

278 40

149-10034 4 ENCLOSURE

PC-J3624 MK

also in bus with evidine was a small white box with a few feet of tape on its reel. These tag # 3m 8998


149-10024-4

We antiface 12/15/22


149-10024-4

pured tape (magnetic?)
appropriation + number of questioned speaks my first


				b					A 201	14	9)0	24	° - 4	
								-						. *	
					\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.										



149-10024-4



149-10024-4





149-100 24-4

	REC-163 149-10024-5	
, fi	George J. Kidera, M. D. Vice President Medical Services United Air Lines Post Office Box 66100 Chicago, Illinois 60666 Dear Dr. Kidera:	b6 b7C
	Special Agent Ponder has shown me your letter of December 14th. You were indeed thoughtful to write and comment as you did regarding his efforts and those of Messrs. and and in connection with their duties as members of the FBI's Disaster Squad. We share their appreciation for your complimentary remarks.	
	We want you to know that this Bureau always stands ready to assist in these matters.	
Cun	Sincerely yours, For the Acting Director W. MARK FELT W. Mark Felt Acting Associate Director	
	1 - Chicago - Enclosure 1 - Mr. Purvis - Enclosure	
	Personal Attention: Bring to the attention of SA Beverly Ponder and Fingerprint Examiners and	у Е.
elt aker allahan leveland onrad	1 - Personnel File of SA Beverly E. Ponder - Enclosure 1 - Personnel File of Mr Enclosure 1 - Personnel File of Mr Enclosure 1 - Personnel File of Mr Enclosure	b6 b70
albey ebhardt enkins farshall filler, E.S	NOTE: Bufiles disclose prior correspondence with Dr. Kidera on similar matters.	
Vurvis	JWD: la 1973 WAL DOOM TELETYPE UNIT	

UNITED AIR LINES

EXECUTIVE OFFICES

1200 ALGONQUIN ROAD, ELK GROVE TOWNSHIP, ILLINOIS MAILING ADDRESS: P. O. BOX 66100 - CHICAGO, ILLINOIS, 60666

OFFICE OF THE VICE PRESIDENT MEDICAL SERVICES

TEL.
AC 312 952-6103
AC 312 952-4648

December 14, 1972

MR. Beverly E. Ponder
Federal Bureau of Investigation
Washington, D. C. 20535

Washington, D. C. 20535

Dear Bev:

It was indeed gratifying to have you,

and make an appearance at the Cook County

Morgue.

It was quite evident on initially viewing the bodies as they were brought into the morgue that we would again be dependent on the fine services of your office to provide us with identification.

The diligence and cooperation of the FBI Disaster Team coupled with United's Disaster Team provided an ideal working arrangement. Without the expertise you displayed, I am certain many of the bodies would not have been identified.

On behalf of United Air Lines, I cannot thank you enough for your splendid efforts.

Sincerely yours,

REC- 103

George J. Kidera, M.D.

Vice President

Medical Services

GJK:dc

N. No. To

7 DEC 27 1972

CONESPONDENCE

b6

b7C

do

OPTIONAL FORM NO. 10 MAY 1962 EDITION GALGERY: REG. NO. 27 UNITED STATES GO

Memorandum

: MR. FELT

DATE: 12-12-72

J. D. Purvis

SUBJECT: CRASH OF UNITED AIRLINES FLIGHT #553

CHICAGO, ILLINOIS

Mrs. Neenan __ 12-8-72 IDENTIFICATION MATTER The purpose of this memorandum is to record the activities of the FBI

Disaster Squad in connection with captioned crash.

United Airlines Flight #553 crashed while approaching Midway Airport, Chicago, Illinois, at approximately 2:30 P.M., on 12-8-72. The flight originated in Washington, D.C. and was bound for Omaha, Nebraska, with intermediate stop in Chicago carrying 55 passengers and a crew of 6. There were 43 fatalities and 18 survivors. The plane crashed into a string of row houses about one mile from the runway resulting in 2 additional fatalities for a total of 45 including 4 children. It was snowing at the time of the crash and visibility was described as approximately one mile. The cause of the crash has not been determined and an investigation by the National Transportation Safety Board is continuing. According to press reports, it has been established that immediately prior to the crash the tower instructed the pilot to institute a "missed approach procedure" to avoid a private plane which was in the immediate vicinity. Witnesses claim that it sounded as though the pilot attempted to gain altitude and was unsuccessful. Because of the low altitude of the plane there was little impact to the passengers, however, fire ensued which was fed by a ruptured gas line and the majority of the victims were severely charred. Request for assistance of the FBI Disaster Squad was made a few hours following the crash by James B. Conlisk, Jr., Superintendent of Police. Chicago, Illinois. United Airlines officials joined Superintendent Conlisk in the requesta

> The Disaster Squad consisting of Latent Fingerprint Examiners and Section-Chief DECE Ponder

departed Washington, D.C., 7:30 A.M., 12-9-72, and proceeded to the Cook County, Illinois, morgue. The victims had been transported to the morgue during the night of 12-8-72 where they were processed by members of the Chicago Police Department for personal effects. All personal property was removed from the passengers and labeled and remained in the custody of the police department. The identification of the victims was under the supervision of Dr. George Kidera, Vice President of United Airlines. The retease of the bodies and the final determination as to identity

JDP:ljr ()

Enclosures Sent MINCEOSVIE

MAY 15 1973

b6

Cleveland Cenrad Dalhey Gebbardt

Jenkins Marshall Miller, E.S. Purvis _

Sovars Walters Tele. Room Mr. Kinley _

Mr. Armstrong_

Ms. Herwig _

3

.

Memorandum to MR. FELT

RE: CRASH OF UNITED AIRLINES FLIGHT #5.53

CHICAGO, ILLINOIS

12-8-72

IDENTIFICATION MATTER

was under the jurisdiction of Dr. Andrew J. Toman, Coroner of Cook County. It was determined that a number of the victims had been identified through personal effects and or through observation by relatives and friends during the night and were released. The Chicago Police Department had also examined each victim for finger-prints and had obtained prints from 12 of the victims. The Disaster Squad processed the remaining victims in the morgue and was able to secure one or more prints from each of the 16 additional victims. Because of the extreme incineration the fingerprinting was a slow and tedious process and most of the prints obtained came from the second layer of skin. The squad was successful in identifying 12 of the victims through finger-prints. All remaining victims were identified by Dr. Kidera and his staff through personal effects and dental and pathological examination. (List of victims identified is attached).

Personnel of the Chicago Office did an outstanding job in maintaining liaison with United Airlines, Chicago Police Department and the Coroner's Office and the SAC is submitting a recommendation for appropriate recognition.

The Disaster Squad again performed in an outstanding manner working long hours under adverse conditions and was successful in obtaining prints for identification purposes resulting in 12 positive fingerprint identifications. Dr. Kidera expressed appreciation and was most complimentary of the skill exhibited by the Disaster Squad.

RECOMMENDATION:

The members of the Disaster Squad consisting of and B. E! Ponder receive a letter of commendation

for their fine work in this case.

ox we

LETTERS PREPARED 12/15/72.134 -2b7C

RE: CRASH OF UNITED AIRLINES FLIGHT #553 CHICAGO, ILLINOIS 12-8-72

The following is a list of Fingerprint Identifications made by FBI Disaster Squad on 12-9/10-72. The dates of birth are listed as shown on the fingerprint cards.

Body Number	<u>Identity</u>				
73	Ralph Pertl Blodgett, born 10-21-28, fingerprinted in connection with enlistment in the Military Service.				
74	James Richard West, born 5-1-17, fingerprint in connection with enlistment in the Military Service.				
75	Barry Jon Elder, born 9-1-41, fingerprinted in connection with his employment with United Airlines.				
80	W. Roger Rossman, born 3-31-18, fingerprinted in connection with U.S. Government employment.				
82	Harold Maurice Jordan, born 9-8-15, fingerprinted in connection with U.S. Government employment.				
83	Wendell Lewis Whitehouse, born 6-4-28, fingerprinted in connection with Defense Program.				
85	France William Ellison, born 11-1-35, fingerprinted in connection with U.S. Government employment.				
87	John Richard Beshoar, born 4-7-26, fingerprinted in connection with enlistment in the Military Service.				
88	Theodore Gregory Baldwin, born 6-5-30, fingerprinted in connection with enlistment in U.S. Naval Reserve.				
109	Kenneth Max Shull, born 4-26-30, fingerprinted in connection with Military Service.				
110	Christine Elizabeth Hewitt, born 6-24-49, fingerprinted in connection with U.S. Government employment.				
125	Richard Allan Knowland, born 10-8-36, fingerprinted in connection with Military Service.				

Dr. George Kidera of United Airlines was advised as the above identifications were made and they were posted to the master list of passengers maintained by the Disaster Squad.

749-10024-6



FEDERAL BUREAU OF INVESTIGATION LATENT FINGERPRINT SECTION WORK SHEET

	I	LATENT FINGER	RPRINT SECTI	ON WORK SHEE	ET	. . €
		2;50 p.m.	te	Reference N FBI File No		10011-1
Receive	_{ed:} 12-14-72			Latent Case	. , ,	4796
Answer	to: Mr. Jame Illinois	s B. Conlis 60601.	sk, Jr. Su	perintender	t of Polic	e, Chicago
Examin	ation requested l	y: Addressee				b
Copy to	:					·
RE:	CHICAGO, 12-8-72	F UNITED AIR ILLINOIS CATION MATT		HT 4 553		
Date of Specime	reference commu	inication: Reg Chi	enest by	Conlisk (a by teleps	rove) thr hone 12	w SAC 18/72
Bodies of	f 37 a	leceased			rash).	examina
Rema	ining N	bodies.	idesity	heaf by	other.	means
Total	alof in pra	43 dec	eased			
Result o	of examination:			Examination Evidence no	_	
So.	me fing	resprinto	oftae	ned fr	om 28	b6 b7c
bode	17	no fin	gerprin	· D.	tained	
Tho.	dies M	/		2 rolen	supred .	P
finger	prints Se	e attac	hed per	ages).	· P	1700
no copi	export s	g out of	galed Burea	by M	r, Vonc	(antinued)
Examina	ution completed	Time	· Date	Dictated	Data /	on attacked

Page I, addendum to work sheet Body #s used are those placed thereon by Cook County Morgue (do not run consecutively). Thingerprints from 12 bodies taken by Chicago T.D., but some sheeked and all compared by disaster squad: No fingerprints obtained from body-hands completely mangled + burned - Male chicago P.D. - all of left hand Male No fingerprints - hands completely burned off Identified by fingerprints as Balph Pertl Blodgett male Complete set of prints taken by chicago of. Sansfifiedlas James Richard West Male Prints of left hand taken by Chicago V.D. Male Stentified as Barry Jon Elder by fingerprines no fingerprints obtained from body Fresnale 77 Protable female - 3 fingers of left hand-not identified by fests.

PAGE 2 Body # Hingers of left hand - female-not all jungers it hand-2 for left hand-ferrale-noted by finger facints 79 # 1 finger + all fingers of left hand-onde identified by fingerprists as W. Roger Jossman 80 81 Tingerprints of left thumb only - femalenot Oby gets. 82 Fingerprint of 1st. thush and several Jingers left hand-male-identified as Harold Manrice Jordan I fingerprints of rt hand and all of left hand-male-identified as Wendell Lewis Whitehouse 83 I fingerprient of left thumb-male-silentic fiel as France William Ellison 85 No fingerprints I arm gone-sheother hand not printable white male 86

PAGE 3 Body# 2 fingesprinte of st. hand-male-identified as John Richard Bestour Complete set of prints - male identified as Theodore Gregory Baldwin 88 2 fingerfrints of it hand-male-not identified with known grints Ifingerfrint it hand-male not identified with known prints 89 5 fingerfrints pt. hand, 4 fingerprints left hand-male-mot identified with Brown prints Frankle Sill - not printed Jingerprint left hand-female-not identified with known prints Hingerprint st. hand - yfingerprints lift hand-not ident with known prints male

Page 4 Body# I fingerfrent st. Band, 2 of left hand not ident with known prints. Formale 2 fingerprints it hand, If the left hand not identical with Senows prints I fingerprint from left hand-unable to determine which finger-not o with known prints 104 Fingers completely burned - no prints 105 Finale child-scot priggsprinted-no known printe for this description. 106 Hingerjarent from left hand-not select with known prints male 107 Fingerprints from 3 fingers of left brank-not o with known prints. Fremale Fingerprints from left thumb & index -Shull fingerprints Jenneth Max Three Singerprints of hand and all of left hand - O Christine Elizabeth Hewitt 113 Hands completely burned- no fingerprints

115 Hands completely burned-no fingerprints 124 Hands completely burned- no fingerprents 125 Ifingerprint, left index—identified as Gichard allen Knowland Isot of fots taken by thicago, P.D. and Sateled as from body # 91 - but which were actually from some other body, # not brown - not identified with known fingerprints

CRASH OF UNITED AIR LINES FLIGHT 553
BOEING 737, CHICAGO, ILLINOIS
12/8/72
DAMV

BOEING 737, CHICAGO, ILLI 12/8/72 DAMV

Mr. Baker __ Mr. Callahan Mr. Cleveland Mr. Conrad 2 Mr. Gebhards Mr. Jenkins Mr. Marshall Mr. Miller, E.S. Mr. Soyars _ Mr. Thompson _ Mr. Walters ____ Tele. Room __ Mr. Baise __ Mr. Barnes __ Mr. Bowers _ Mr. Herington ___ Mr. Conmy _ Mr. Mintz ___ Mr. Eardley ___ Mrs. Hogan __

Mr. Felt_

Epper

Egnor

(CRASI')

WASHINGTON (UPI) -- THE FEI HAS ACKNOWLEDGED THAT IT MOVED SWIFTLY TO INVESTIGATE A UNITED AIR LINES CRASH IN CHICAGO MAY 9, FUT SAIR IT WAS NORMAL PROCEDURE AND THAT AGENTS LIFTED NOT EVEN KNOW THAT THE WIFE OFF, WATERGATE COMSPIRATOR E. HOWARD HUNT HAD BEEN KILLED IN THE CRASH-SOME 50 AGENTS WERE ON THE SCENE AS EARLY AS 45 MINUTES AFTER THE

CRASH, IT WAS REVEALED WEDNISDAY.

LETTERS FROM ACTING FEI DIRECTOR WILLIAM RUCKELSHAUS AND JOHN
REED, CHAIRMAN OF THE NATIONAL TRANSPORTATION SAFETY BOARD, WERE
REPLASED WEINESDAY BY A HOUSE GOVERNMENT OPERATIONS SUBCOMMITTEE.

NISB SOURCES HAVE CHARGED THAT THE FBI BARGED IN ON THE
INVESTIGATION OF THE CRASH, IN WHICH THEY WOULD NOT NORMALLY BE
INVOLVED. THE FBI'S EARLY INVOLVEMENT WITH SO MANY AGENTS BAISED

SPECULATION THAT THE FEI SUSPECTED SAPOTAGE.

SOME SPECULATED THAT AGENTS HAD BEEN FOLLOWING MRS. HUNT AND KNEW
SHE WAS ABOARD THE PLANE, WHICH ALSO CARRIED REP. GEORGE COLLINS,
D-ILL., AND 43 OTHERS TO THEIR DEATHS AS IT ATTEMPTED, TO LAND AT.

MIDWAY AIRPORT.

BUT BUCKELHAUS SAID IN A LETTER TO REED ON MONDAY, "THE FACT THAT MRS. E. HOWARD HUNT WAS ABOARD THE FLANE WAS UNKNOWN TO THE FRI AT THE TIME OUR INVESTIGATION WAS INSTITUTED." AGENTS DETERMINED AFTER 20 HOURS THERE WAS NO SABOTAGE. HE SAID.

PROCEED TO THE SCENE OF AN AIRPLANE CRASH FOR THE FURPOSE OF 26 JUN 19 197 BEVELOFING ANY INFORMATION INDICATING A POSSIBLE FEDERAL VIOLATION JUN 19 197 BUTTHIN THE INVESTIGATIVE JURISDICTION OF THE FAI."

TE SAID FEI JURISDICTION INVOLVES INVESTIGATIONS FOR SAPOTAGE OF CHER GRINES ABOARD AIRCRAFT, SICH AS ASSAULT, MURDER OF INTERPERCICE WITH FLIGHT CREW MEMBERS.

FUCEELSHAUS' LETTER DID NOT SHED ANY LIGHT OR WHY THE FEI HIGHT

TAKEN A NUMBER OF MON-TYPICAL ACTIONS RELATING TO THE AGENTS THAT

57 JUN 2 1 1973

WASHINGTON CAPITAL NEWS SERVICE

FRENT

CHARLE AND ENTRY OF THE TONER OF THE TREE OF THE NEW ON CONTROL TO THE TONER AND LISTENED TO THE TONER TAPES EFFORE OUR INVESTIGATORS WAD POWE SO ... THE TONER TO THE TONER TO THE TONER TO PEDERAL AVIATION ADMINISTRATION (FRA) PEDSONNEL AT THE TOWER TO LISTEN TO THE RECORDING MADELAT THE TOWER OF THE CONVERSATION BETWIED THE TOWER AND UNITED AIR LINES FLIGHT 35. AT NO TIME DID SA MARTY EXCUEST TO BE ALLOWED TO LISTEN TO THE TAPES."


[CHARLE MILLER, DIRECTOR OF THE SUREAU OF AVIATION SAFETY FOR USE FOR THE SUREAU OF AVIATION SAFETY FOR USE OF THE SURE OF THE

PRINTS UNITIONTIFIED TRAN RODIES - TAKEN B HOMALO #778 #79 # 96 1110 5

149-10024-6

Probable Fremale L'ADERN DE LEFT HAND 6. Thumb 7. Index finger 8. Middle finger 9. Ring finger 10. Little finger b6 ь7С ma.

6. Thumb 7. Index finger LEFT HAND 8, Middle finger 9. Ring finger 10. Little finger 4



#70

#9 Finger Depm 15 #79 FEM #81 FEM


W Eller

Epidermis





FEM b6 b7C #96 Back side of epideimis



98 W.F. 21mgs 0 ms Hunt (7 inside Epidermis Depmis

Back such #618 # 108 UNIDENTIFIED PRINTS

FROM BODIES -- TAKEN BY FBAI

MALE

ENSA ENSA ENSA ENSA ENSA

#97

#104

91 (Free folder for pet by PD)
97

149-12024-6

W.

ъ7с

b6

Body # 1/ Endex Fibring # 2

F97 PERSON IDENTIFIC	ATION	ST NAME TENTATINE		ME MIDD	DLE NAME SEX RACE HT.(Inches) WT.
R.J.	2. Index finger Sc	RIGHT HAV		Ring finger	A Little finger
· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	ARS AND MARKS	REF.		
See Reverse Side for Fu		*			
1. RIGHT THUMB	LEFT RING	3. RIGHT MIDDI	, q	RIGHT RING	5. RIGHT LITTLE
6. LETTHOMB	7. LEFT INDEX	8. LEFT MIDDL	9. L	EFT RING	10. LEFT LITTLE
4				343. A 44.	i' \$v .
EFT FOUR FINGERS	SIMULIANEOUSLY	LEFT THOMB RIGH	. HUMB RIGHT F	OUR FINGERS TA	KENSIMULTANEQUSLY
e e e e e e e e e e e e e e e e e e e				Ţ,	
*		je v			the second
					× .
•		'			

FEDERAL BUREAU OF INVESTIGATION UNITED STATES DEPARTMENT OF JUSTICE WASHINGTON, D.C. 20537


PERSONAL IDENTIFICATION


To obtain classifiable fingerprints:

- 1. Use printer's ink.
- 2. Distribute ink evenly on inking slab.
- 3. Wash and dry fingers thoroughly.
- 4. Roll fingers from nail to nail, and avoid allowing fingers to slip.
- 5. Be sure impressions are recorded in correct order.
- 6. If an amputation or deformity makes it impossible to print a finger, make a notation to that effect in the individual finger block.

 7. If some physical condition makes it impossible to obtain perfect impressions, submit the best that can be obtained with a
- 7. If some physical condition makes it impossible to obtain perfect impressions, submit the best that can be obtained with a memo stapled to the card explaining the circumstances.
- 8. Examine the completed prints to see if they can be classified, bearing in mind the following:

 Most fingerprints fall into the patterns shown below (other patterns occur infrequently and are not shown here):





- PERSONAL		LAST	NAME	FIRST NAME	MIDDLE NAME	SEX	RACE
1 IDENTIFICATION						101	
FINGERPRINTS SUBMITTED BY		SIGNA	TURE OF PERSON FI	NGERPRINTED		H T.(Inches)	W Т.
		PESIDI	ENCE OF PERSON FI	NCEODOINTED		HAIR	EYES
11 0		RESIDI	ENCE OF PERSON FI	NGERPRINTED			
FINGERPRINTED BY				÷ •		DATE OF	ВІЯТН
Person to be Notified in	Case of Emergency	DATE	FINGERPRINTED	LEAVE THIS SPACE BLA	MK		
NAME		PLACE	OF BIRTH	C L ASS	4.1		*
ADDRESS	-	CITIZE	NSHIP	FFT		$\mathcal{D}^{\mathcal{L}}$	سير
		SCARS	AND MARKS	REF.	10	1	
See Reverse Side for F	urther Instructions			. 4			
1. RIGHT THUMB	2. RIGHT INDEX	»	3. RIGHT MIDDLE	4. RIGHT RI	NG 5.	RIGHT LIT	TLE
				Y			To C
6. LEFTTHEMB	7. LEFFINDEX		8. LEFT MI PENE	9. LEFT RIN	G 10		TLE
			100				
REVERSION FINGERS TO A	EN SIMUL TAN EOUSLY		EFT THUMB RIGHT	THUMB RIGHT FOUR FIN	GERS TAKEN SIMUL	.TANEOUS	- Y


FEDERAL BUREAU OF INVESTIGATION UNITED STATES DEPARTMENT OF JUSTICE WASHINGTON, D.C. 20537

PERSONAL IDENTIFICATION

To obtain classifiable fingerprints:

- 1. Use printer's ink.
- 2. Distribute ink evenly on inking slab.
- 3. Wash and dry fingers thoroughly.
- 4. Roll fingers from nail to nail, and avoid allowing fingers to slip.
- 5. Be sure impressions are recorded in correct order.
- 6. If an amputation or deformity makes it impossible to print a finger, make a notation to that effect in the individual finger block.
- 7. If some physical condition makes it impossible to obtain perfect impressions, submit the best that can be obtained with a memo stapled to the card explaining the circumstances.
- 8. Examine the completed prints to see if they can be classified, bearing in mind the following:

 Most fingerprints fall into the patterns shown below (other patterns occur infrequently and are not shown here):



b7C EFFTINGER ENTINGER

UNIDENTIFIED FRATS

FROM BODIES - TAKEN BY

CHICAGO FD

MALE

HONOR HONOR

du see folder for josts by FBD

19-1024-6







PHOTO AVAILABLE? YES NO	INSTRUCTIONS				
IF AVAILABLE, PASTE PHOTO OVER INSTRUCTIONS IN DOTTED AREA. (DO NOT USE STAPLES)	1. UNLESS OTHERWISE PROVIDED BY REGULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IM- MEDIATELY FOR MOST EFFECTIVE SERVICE.				
SINCE PHOTOGRAPH MAY BECOME DETACHED INDICATE NAME, DATE TAKEN, FBI NUMBER, CONTRIBUTOR AND ARREST NUMBER ON REVERSE SIDE, WHETHER ATTACHED TO FINGERPRINT CARD OR SUBMITTED LATER.	2. FINGERPRINTS SHOULD BE SUBMITTED BY <u>ARRESTING AGENCY ONLY</u> (MULTIPLE PRINTS ON SAME CHARGE SHOULD <u>NOT</u> BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.). REQUEST COPIES OF FBI IDENTIFICATION RECORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE.				
ARREST FINGERPRINTS SENT FBI PREVIOUSLY AND FBI NO. UNKNOWN,	3. TYPE OR PRINT ALL INFORMATION. 4. NOTE AMPUTATIONS IN PROPER FINGER BLOCKS.				
TATUTE CITATION (SEE INSTRUCTION NO. 9) CIT	5. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUB- MIT LATER ON FBI FORM R.84 FOR COMPLETION OF RECORD. IF FINAL DISPOSI- TION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION, c. 9., RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO, IN THE ARREST DISPOSI- TION BLOCK PROVIDED ON THIS SIDE.				
	6. MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.				
	7. CAUTION - CHECK BOX ON FRONT IF CAUTION STATEMENT INDICATED. BASIS FOR CAUTION (ICO) MUST GIVE REASON FOR CAUTION, o. g., ARMED AND DANGEROUS,				
RREST DISPOSITION (SEE INSTRUCTION NO. 5) ADM	SUICIDAL, ETC. 8. MISCELLANEOUS NUMBER (MNU) - SHOULD INCLUDE SUCH NUMBERS AS MILITARY " SERVICE, PASSPORT AND/OR VETERANS ADMINISTRATION (IDENTIFY TYPE OF NUM- BER).				
MPLOYER: IF U.S. GOVERNMENT, INDICATE SPECIFIC AGENCY. IF MILITARY, LIST BRANCH OF SERVICE AND SERIAL NO.	9. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (oxample - PL for PENAL LAW) AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS.				
	10. ALL INFORMATION REQUESTED IS ESSENTIAL.				
CCUPATION ESIDENCE OF PERSON FINGERPRINTED	SEND COPY TO:				
CARS, MARKS, TATTOOS. AND AMPUTATIONS <u>SMT</u>	REPLY DESIRED? YES NO (REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED)				
ASIS FOR CAUTION ICO	IF COLLECT WIRE OR COLLECT TELEPHONE REPLY DESIRED, INDICATE HERE: (WÎRE SENT ON ALL UNKNOWN DECEASED) WIRE REPLY TELEPHONE REPLY TELEPHONE NO. AND AREA CODE				
ATE OF OFFENSE DOO SKIN TONE SKN	LEAVE BLANK				
ISC. NO. MNU					
NIDENTIFIED DEAD FROM A PLANE CRAP FDEC 72 AT 3714 W 71 ST. PRINTED AT COOK COUNTY MORGUE 8 DEC. 72	LEAVE BLANK				




26376 FEDERAL I		UNITED STATES DEPARTMENT OF JUSTICE DN, D. C. 20537				
SINCE PHOTOGRAPH MAY BECOME D DATE TAKEN, PBI NUMBER, CONTRI ON REVERSE SIDE, WHETHER ATTAC SUBMITTED LATER.	YES NO O OVER INSTRUCTIONS E STAPLES) ETACHED INDICATE NAME, BUTOR AND ARREST NUMBER HED TO FINGERPRINT CARD OR PREVIOUSLY AND FBI NO. UNKNOWN, DATE	INSTRUCTIONS I. UNLESS OTHERWISE PROVIDED BY RECULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IMMEDIATELY FOR MOST EFFECTIVE SERVICE. I. FINGERPRINTS SHOULD BE SUBMITTED BY ARRESTING AGENCY ONLY (MULTIPLE PRINTS ON SAME CHARGE SHOULD NOT BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.). REQUEST COPIES OF FBI IDENTIFICATION RECORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE. I. TYPE OR PRINT ALL INFORMATION. I. NOTE AMPUTATIONS IN PROPER FINGER BLOCKS. I. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUBMIT LATER ON FBI FORM ROA FOR COMPLETION OF RECORD. IF FINAL DISPOSITION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION. 6. 8; RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO; IN THE ARREST DISPOSITION BLOCK PROVIDED ON THIS SIDE.				
2.	•					
3.		6. MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.				
		T. CAUTION - CHECK BOX ON FRONT, IF CAUTION STATEMENT INDICATED. BASIS FOR CAUTION (ICO) MUST GIVE REASON FOR CAUTION, 6. g., ARMED AND DANGEROUS,				
ARREST DISPOSITION (SEE INSTRUCTION	NO. 5) <u>ADM</u>	SUICIDAL, ETC. 8. MISCELLANEOUS NUMBER (MNU) - SHOULD INCLUDE SUCH NUMBERS AS MILITARY SERVICE, PASSPORT AND/OR VETERANS ADMINISTRATION (IDENTIFY TYPE OF NUM- BER).				
EMPLOYER: IF U. S. GOVERNMENT, INDICATE IF MILITARY, LIST BRANCH OF S		P. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (example - PL for PENAL LAM AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS. 10. ALL INFORMATION REQUESTED IS ESSENTIAL.				
OCCUPATION		SEND COPY TO:				
		,				
RESIDENCE OF PERSON FINGERPRINT	ED .					
SCARS, MARKS, TATTOOS, AND AMP	UTATIONS <u>SMT</u>	REPLY DESIRED? **(REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED) IF COLLECT WIRE OR COLLECT TELEPHONE REPLY				
BASIS FOR CAUTION ICO		DESIRE®, INDICATE HERE: (WIRE SENT ON ALL UNKNOWN DECEASED) WIRE REP. TELEPHONE REPLY TELEPHONE NO. AND AREA CODE				
DATE OF OFFENSE DOO	SKIN TONE SKN	LEAVE BLANK				
MISC. NO. MNU						
CRASH 8 DEC 72	AL INFORMATION A PLANT AD I-ROM A PLANT AT 3714 W 71 ST. COOK COUNTY MORGO - 456-362	LEAVE BLANK				



	YES NO			
PHOTO AVAILABLE?				
IF AVAILABLE, PASTE PHOTO OVER INSTRUCTIONS IN DOTTED AREA. (DO NOT USE STAPLES) SINCE PHOTOGRAPH MAY BECOME DETACHED INDICATE NAME, DATE TAKEN, FBI NUMBER, CONTRIBUTOR AND ARREST NUMBER ON REVERSE SIDE, WHETHER ATTACHED TO FINGERPRINT CARD OR SUBMITTED LATER.		1. UNLESS OTHERWISE PROVIDED BY REGULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IM- MEDIATELY FOR MOST EFFECTIVE SERVICE. 2. FINGERPRINTS SHOULD BE SUBMITTED BY ARRESTING AGENCY ONLY (MULTIPLE PRINTS ON SAME CHARGE SHOULD NOT BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.). REQUEST COPIES OF FBI IDENTIFICATION REC- ORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE.		
URNISH ARREST NO.	DAYE	5. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUB-		
TATUTE CITATION (SEE INSTRUCTION)	NO. 9) <u>CIT</u>	MIT LATER ON FBI FORM R.B4 FOR COMPLETION OF RECORD. IF FINAL DISPOSI- TION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION, c. g., RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO, IN THE ARREST DISPOSI- TION BLOCK PROVIDED ON THIS SIDE.		
		6. MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.		
		7. CAUTION - CHECK BOX ON FRONT IF CAUTION STATEMENT INDICATED. BASIS FOR		
RREST DISPOSITION (SEE INSTRUCTION	IN NO. 5) ADN	CAUTION (ICO) MUST GIVE REASON FOR CAUTION, c. 9., "ARMED AND DANGEROUS, SUICIDAL, ETC.		
		8. MISCELLANEOUS NUMBER (MNU) - SHOULD INCLUDE SUCH NUMBERS AS MILITARY SERVICE, PASSPORT AND/OR VETERANS ADMINISTRATION (IDENTIFY TYPE OF NUMBER).		
MPLOYER: IF U. S. GOVERNMENT, INDICA IF MILITARY, LIST BRANCH OF		9. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (example - PL for PENAL LAW) AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS. 10. ALL INFORMATION REQUESTED IS ESSENTIAL.		
CCUPATION	·	SEND COPY TO:		
ESIDENCE OF PERSON FINGERPRIF	ITED .			
CARS, MARKS, TATTOOS, AND AM	PUTATIONS SMT	REPLY DESIRED? YES NO		
BASIS FOR CAUTION ICO		REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED)		
		IF COLLECT WIRE OR COLLECT TELEPHONE REPLY DESIRED, INDICATE HERE: (WIRE SENT ON ALL JUKNOWN DECEASED) WIRE REPLY TELEPHONE REPLY TELEPHONE NO. AND AREA CODE		
ATE OF OFFENSE DOO	SKIN TONE SKN	LEAVE BLANK		
ISC. NO. MNU				
ADDITIONAL INFORMATION		LEAVE BLANK		



	HINGTON, D. C. 20537
PHOTO AVAILABLE? YES NO .	INSTRUCTIONS
IF AVAILABLE, PASTE PHOTO OVER INSTRUCTIONS IN DOTTED AREA. (DO NOT USE STAPLES)	1. UNLESS OTHERWISE PROVIDED BY REGULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IM- MEDIATELY FOR MOST EFFECTIVE SERVICE.
SINCE PHOTOGRAPH MAY BECOME DETACHED INDICATE NAME, DATE TAKEN, FBI NUMBER, CONTRIBUTOR AND ARREST NUMBER ON REVERSE SIDE, WHETHER ATTACHED TO FINGERPRINT CARD OR SUBMITTED LATER.	 FINGERPRINTS SHOULD BE SUBMITTED BY ARRESTING AGENCY ONLY (MULTIPLE PRINTS ON SAME CHARGE SHOULD NOT BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.). REQUEST COPIES OF FBI IDENTIFICATION REC- ORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE.
ARREST FINGERPRINTS SENT FBI PREVIOUSLY AND FBI NO. UNKNOW	3. TYPE OR PRINT ALL INFORMATION.
URNISH ARREST NO DATE	4. NOTE AMPUTATIONS IN PROPER FINGER BLOCKS.
TATUTE CITATION (SEE INSTRUCTION NO. 9) CIT	5. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUB- MIT LATER ON FBI FORM R-04 FOR COMPLETION OF RECORD. IF FINAL DISPOSI- TION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION, 0. 9., RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO, IN THE ARREST DISPOSI- TION BLOCK PROVIDED ON THIS SIDE.
•	6. MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.
	7, CAUTION - CHECK BOX ON FRONT IF CAUTION STATEMENT INDICATED. BASIS FOR CAUTION (ICO) MUST GIVE REASON FOR CAUTION, o. g., ARMED AND DANGEROUS,
RREST DISPOSITION (SEE INSTRUCTION NO. 5) ADM . : .	SUICIDAL, ETC.
*	8. MISCELLANEOUS NUMBER (MNU) - SHOULD INCLUDE SUCH NUMBERS AS MILITARY. SERVICE, PASSPORT AND/OR VETERANS ADMINISTRATION (IDENTIFY TYPE OF NUMBER).
MPLOYER: IF U. S. GOVERNMENT, INDICATE SPECIFIC AGENCY. IF MILITARY, LIST BRANCH OF SERVICE AND SERIAL NO.	9. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (Oxomple - PL for PENAL LAW) AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS. 10. ALL INFORMATION REQUESTED IS ESSENTIAL.
OCUPATION	SEND COPY TO:
CCUPATION	SEND COPY 10:
ESIDENCE OF PERSON FINGERPRINTED	
CARS, MARKS, TATTOOS. AND AMPUTATIONS SMT	REPLY DESIRED? YES NO
	:(REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED)
	IF COLLECT WIRE OR COLLECT TELEPHONE REPLY DESIRED, INDICATE HERE: (WIRE SENT ON ALL UNKNOWN DECEASED)
ASIS FOR CAUTION ICO	WIRE REPLY TELEPHONE REPLY TELEPHONE NO. AND AREA CODE
ATE OF OFFENSE DOO SKIN TONE SKN	LEAVE BLANK
ISC. NO. MNU	
NIDENTIFIED DEAD FROM A PLANE	CRAS/ LEAVE BLANK
DEC72 AT 3714 W 71 ST. PRIN	Teb
T COOK COUNTY MORGUE 8 DEC.	プゥ



26397 FEDERAL BU		UNITED STATES DEPARTMENT OF JUSTICE N, D. C. 20537	
PHOTO AVAILABLE?	ES NO	INSTRUCTIONS	
IF AVAILABLE, PASTE PHOTO (IN DOTTED AREA. (DO NOT USE ST		1. UNLESS OTHERWISE PROVIDED BY REGULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IM- MEDIATELY FOR MOST-EFFECTIVE SERVICE.	
SINCE PHOTOGRAPH MAY BECOME DETA DATE TAKEN, FBI NUMBER, CONTRIBUTO ON REVERSE SIDE, WHETHER ATTACHED SUBMITTED LATER.	OR AND ARREST NUMBER	 FINGERPRINTS SHOULD BE SUBMITTED BY <u>ARRESTING AGENCY ONLY</u> (MULTIPLE PRINTS ON SAME CHARGE SHOULD <u>NOT</u> BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.). REQUEST COPIES OF FBI IDENTIFICATION REC- ORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE. 	
		3. TYPE OR PRINT ALL INFORMATION.	
IF ARREST FINGERPRINTS SENT FBI PRI FURNISH ARREST NO.		4. NOTE AMPUTATIONS IN PROPER FINGER BLOCKS.	
STATUTE CITATION (SEE INSTRUCTION NO. 9) <u>CIT</u> 1.		5. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUB- MIT LATER ON FBI FORM R-84 FOR COMPLETION OF RECORD. IF FINAL DISPOSI- TION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION, o. g., RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO, IN THE ARREST DISPOSI- TION BLOCK PROVIDED ON THIS SIDE.	
2.	·	6. MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.	
3.		7. CAUTION - CHECK BOX ON FRONT IF CAUTION STATEMENT INDICATED. BASIS FOR CAUTION (ICO) MUST GIVE REASON FOR CAUTION, e. g., ARMED AND DANGEROUS,	
ARREST DISPOSITION (SEE INSTRUCTION NO.	5) <u>ADM</u>	SUICIDAL, ETC. 8. MISCELLANEOUS NUMBER (MNU) - SHOULD INCLUDE SUCH NUMBERS AS MILITARY SERVICE, PASSPORT AND/OR VETERANS ADMINISTRATION (IDENTIFY TYPE OF NUMBER).	
EMPLOYER: IF U. S. GOVERNMENT, INDICATE SPE IF MILITARY, LIST BRANCH OF SERV		9. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (Oxemple - PL for PENAL LAW) AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS. 10. ALL INFORMATION REQUESTED IS ESSENTIAL.	
-OCCUPATION	! -	SEND COPY TO:	
RESIDENCE OF PERSON FINGERPRINTED			
		, A. V.	
SCARS, MARKS, TATTOOS, AND AMPUT	ATIONS <u>SMT</u>	REPLY DESIRED? YES NO	
		REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED	
7,010,000		IF COLLECT WIRE OR COLLECT TELEPHONE REPLY DESIRED, INDICATE HERE: (WIRE SENT ON ALL UNKNOWN DECEASED)	
BASIS FOR CAUTION 120		WIRE REPLY TELEPHONE REPLY TELEPHONE NO. AND AREA CODE	
DATE OF OFFENSE DOO	SKIN TONE SKN	LEAVE BLANK	
MISC. NO. MNU	. ,		
WIVE WILEIED DEAD	INFORMATION EROM PLANE CRASHO.	LEAVE BLANK	
BRIVE 8 DEC 72	PRINTED AT C.C.		
FD-249 (REV. 4-26-71) × GPO: 1972 O -	456-362 £1 263	397	




PHOTO AVAILABLE? YES NO	
PROTO AVAILABLE:	INSTRUCTIONS
IF AVAILABLE, PASTE PHOTO OVER INSTRUCTIONS IN DOTTED AREA. (DO NOT USE STAPLES)	UNLESS OTHERWISE PROVIDED BY REGULATION IN YOUR STATE, FINGERPRINTS ARE TO BE SUBMITTED DIRECTLY TO FBI IDENTIFICATION DIVISION. FORWARD IMMEDIATELY FOR MOST EFFECTIVE SERVICE.
SINCE PHOTOGRAPH MAY BECOME DETACHED INDICATE NAME, DATE TAKEN, FBI NUMBER, CONTRIBUTOR AND ARREST NUMBER ON REVERSE SIDE, WHETHER ATTACHED TO FINGERPRINT CARD OR SUBMITTED LATER.	2, FINGERPRINTS SHOULD BE SUBMITTED BY ARRESTING AGENCY ONLY (MULTIPLE PRINTS ON SAME CHARGE SHOULD NOT BE SUBMITTED BY OTHER AGENCIES SUCH AS JAILS, RECEIVING AGENCIES, ETC.), REQUEST COPIES OF FBI IDENTIFICATION RECORD FOR ALL OTHER INTERESTED AGENCIES IN BLOCK BELOW. GIVE COMPLETE MAILING ADDRESS, INCLUDING ZIP CODE.
	TYPE OR PRINT ALL INFORMATION.
F ARREST FINGERPRINTS SENT FBI PREVIOUSLY AND FBI NO. UNKNOWN, URNISH ARREST NO DATE	4. NOTE AMPUTATIONS IN PROPER FINGER BLOCKS.
STATUTE CITATION (SEE INSTRUCTION NO. 9) CIT	5. LIST FINAL DISPOSITION IN BLOCK ON FRONT SIDE. IF NOT NOW AVAILABLE, SUB- MIT LATER ON FBI FORM: R-84 FOR COMPLETION OF RECORD. IF FINAL DISPOSI- TION NOT AVAILABLE SHOW PRE-TRIAL OR ARRESTING AGENCY DISPOSITION, o. g., RELEASED, NO FORMAL CHARGE, BAIL, TURNED OVER TO, IN THE ARREST DISPOSI- TION BLOCK PROVIDED ON THIS SIDE.
2.	& MAKE CERTAIN ALL IMPRESSIONS ARE LEGIBLE, FULLY ROLLED AND CLASSIFIABLE.
3.	7. CAUTION - CHECK BOX ON FRONT IF CAUTION STATEMENT VIOICATED. BASIS FOR
ARREST DISPOSITION (SEE INSTRUCTION NO. 5) ADM	CAUTION (ICO) MUST GIVE REASON FOR CAUTION, o. g., ARMED AND DANGEROUS, SUICIDAL, ETC.
ALLES SIGNATION (SEE MATROCHORIO. S. ASTO	E. MISCELLANEOUS NUMBER (MNU) : SHOULD INCLUDE SUCH NUMBERS AS MILITARY SERVICE, PASSPORT AND/OR VETERANG ADMINISTRATION (IDENTIFY TYPE OF NUM- BER).
MPLOYER: IF U. S. GOVERNMENT, INDICATE SPECIFIC AGENCY. IF MILITARY, LIST BRANCH OF SERVICE AND SERIAL NO.	9. PROVIDE STATUTE CITATION, IDENTIFYING SPECIFIC STATUTE (example PL for PENAL LAW) AND CRIMINAL CODE CITATION INCLUDING ANY SUB-SECTIONS. 11. ALL INFORMATION REQUESTED IS ESSENTIAL.
OCCUPATION	SEND COPY TO:
ESIDENCE OF PERSON FINGERPRINTED	
CARS, MARKS, TATTOOS, AND AMPUTATIONS SMT	REPLY DESIRED? YES NO
	: (REPLY WILL BE SENT IN ALL CASES IF SUBJECT FOUND TO BE WANTED)
	- IF COLLECT WIRE OR COLLECT TELEPHONE REPLY DESIRED, INDICATE HERE: (WIRE SENT ON ALL UNKNOWN DECEASED)
BASIS FOR CAUTION ICO	WIRE REPLY TELEPHONE REPLY TELEPHONE NO. AND AREA CODE
DATE OF OFFENSE DOO SKIN TONE SKN	LEAVE BLANK
AISC. NO. MNU	-
NIDENTIFIED DEAD FROM A PLANE CRASH DEC 72 AT 3714 W 7157. PRINTED AT	LEAVE BLANK

GEDERAL DUREAU, OF INVESTIGATION COMMUNICATIONS SECTION


UH 0 6 1373

NRØ17 CG PLAIN

642PM URGENT 6-6-73 RWR

TO ACTING DIRECTOR (149-10024)

FROM CHICAGO (149-1060)



CRASH OF UNITED AIRLINES FLIGHT 553, BOEING 737, CHICAGO, ILLINO

12-872. DAMV. 00: CHICAGO.

RE BUREAU FACSIMILE THIS DATE.

FOR INFO OF BUREAU, RESULTS OF ALL INVESTIGATION CONDUCTED BY THE CHICAGO OFFICE CONCERNING CAPTIONED CRASH WERE MADE AVAIL-ABLE TO THE NATIONAL TRANSPORTATION SAFETY BOARD (NTSB) IMMEDIATELY AFTER IT WAS DETERMINED THAT THERE WAS APPARENTLY NO VIOLATION OF THE DAMV STATUTE IN THIS CRASH. THERE IS NO FURTHER INFORMATION IN THE CHICAGO FILE CONCERNING THIS CRASH. THIS INFORMATION WAS FURNISHED TO NTSB ON DECEMBER 11. 1972. AS THE BUREAU IS AWARE, THE PURPOSE OF THE FBI INVESTIGATION WAS TO DETERMINE IF THERE WAS A VIOLATION OF THE DAMV STATUTE IN CONNECTION WITH THE CRASH. APPROXIMATELY 50 PERSONNEL ARRIVED AT THE SCENE OF THE CRASH, STARTING WITHIN 45 MINUTES OF THE CRASH AND CONTINUING_FOR ADDITIONAL HOUR. AGENTS WERE DISPATCHED TO THE TOWER AT MIDWAY AND TO INTERVIEW FLIGHT ATTENDANTS INASMUCH AS THESE WERE LOGICAL INVESTIGATIVE STEPS TO DETERMINE IF THERE JUN 20 1973 WAS A POSSIBILITY OF SABOTAGE IN THE CRASH OF THE AIRCRAET END PAGE ONE

Mr. Bd Mr. Callahan

Mr. Cleveland

Mr. Conrad Mr. Gebhard

Mr. Jenkins Mr. Marshall

Mr. Miller, E.S. Mr. Soycas

Mr. Thompson

Mr. Walters . Tele. Room .

Mr. Boise . Mr. Barnes .

Mr. Bowers .

Mr. Herington . Mr. Conmy .

Mr. Mintz . Mr. Eardley .

Mrs. Hogan

PAGE TWO

THE FACT THAT AGENTS ARRIVED BEFORE NTSB INVESTIGATORS

IS CERTAINLY NO REFLECTION ON THE FBI, BUT PERHAPS ON NTSB. THE

TECHNICAL ABILITY OF THE AGENTS WHO RECOGNIZED THE STALL SIGNAL IN

THE VOICE RECORDER OCCASIONED SOME COMMENT FROM NTSB INASMUCH AS

THEY WERE OBVIOUSLY NOT AWARE OF THE ABILITIES OF OUR INVESTIGATORS.

THERE WAS NOTHING UNUSUAL ON THE PART OF THE FBI IN ITS INVESTIGATION NOR WAS IT A NON-TYPICAL INVESTIGATIVE PROCEDURE. THE CHICAGO OFFICE DISPATCHED SUFFICIENT PERSONNEL TO CONDUCT INVESTIGATION

IN AN EFFORT TO DETERMINE IF THERE WAS A VIOLATION. WHEN IT WAS DEVELOPED THAT THERE APPARENTLY WAS NO VIOLATION OVER WHICH THIS BUREAU HAD JURISDICTION ALL OUR INFORMATION WAS TURNED OVER TO NTSB. NTSB HAS RECEIVED COPIES OF ALL INTERVIEWS CONDUCTED BY THE FBI IN THIS INVESTIGATION AND THERE IS NOTHING WHATSOEVER IN THE CHICAGO FILE WHICH COULD BE ADDED TO THE INFORMATION ALREADY FURNISHED.

IT IS POINTED OUT THAT AT THE SCENE OF THE CRASH, NTSB INVESTIGATORS AND FAA REPRESENTATIVES AS WELL AS REPRESENTATIVES OF
UNITED AIRLINES WERE MOST APPRECIATIVE OF THE ACTIONS OF THE FBI.
AT NO TIME DID THE FBI INTERFERE WITH THE ACTIONS OF THE CHICAGO
END PAGE TWO

PAGE THREE

PD OR WITH THE CHICAGO FIRE DEPARTMENT, ONHOM RESPONSIBILITY
RESTED TO SECURE THE SITE OF THE CRASH AND TO CONTROL THE CROWDS.
CHICAGO PD ALSO EXPRESSED APPRECIATION OF FBI PRESENCE AT
CRASH SCENE.

IT IS POINTED OUT ALSO THAT IN THE LETTER TO ACTING DIRECTOR RUCKELSHAUS FROM JOHN H. REED IT IS MENTIONED THAT MRS. E. HOWARD HUNT WAS KILLED IN THE CRASH AND SHE IS THE WIFE OF AN INDIVIDUAL CONNECTED IN THE WATERGATE INVESTIGATION. FOR THE INFORMATION OF THE BUREAU. THE CHICAGO OFFICE WAS NOT AWARE OF THIS RELATION-SHIP AT THE TIME IT ARRIVED AT THE SCENE OF THE CRASH AND WAS NOT AWARE OF HER IDENTITY UNTIL THE FBI PRELIMINARY INVESTIGATION WAS COMPLETED. THE FACT THAT SHE WAS ABOARD THAT AIRCRAFT HAD ABSOLUTELY NOTHING TO DO WITH FBI ACTION IN THIS INSTANCE. FACT THAT \$10.000 WAS FOUND IN THE POSSESSION OF MRS. HUNT BY PERSONS WHO WERE CONDUCTING SALVAGE OPERATIONS OF THE AIRCRAFT ALSO OCCURRED AFTER THE FBI HAD REMOVED ITSELF FROM THE IMMEDIATE INVESTIGATION. IT IS POINTED OUT THAT THERE WAS ABSOLUTELY NO REASON FOR ANYBODY TO MAKE AN ALLEGATION THAT THE FBI PARTICIPATED IN THIS INVESTIGATION BECAUSE IT WAS CONNECTED WITH WATERGATE. END PAGE THREE

PAGE FOUR

HOLD

IT IS ALSO POINTED OUT THAT THE DISASTER SQUAD FROM THE IDENTIFICATION DIVISION ARRIVED IN CHICAGO SHORTLY AFTER THE DISASTER AND IN COOPERATION WITH UNITED AIRLINES, THE CHICAGO PD EFFECTED IDENTIFICATION OF THE DEAD PASSENGERS. THIS WAS ROUTINE INVESTIGATION ON THE PART OF THE FBI AND HAD ABSOLUTELY NO CONNECTION WITH A POSSIBLE DAMY VIOLATION.

IT IS AGAIN REITERATED THERE WAS ABSOLUTELY NOTHING UNUSUAL OR UNTYPICAL IN THE FBI'S PARTICIPATION OF THIS CRASH. THE IN-VESTIGATION OF THE ACTUAL CRASH WAS TERMINATED WITHIN 20 HOURS OF THE ACCIDENT AND ALL PERTINENT INFORMATION FURNISHED TO NTSB. FEDERAL BUREAU OF INVESTIGATION COMMUNICATIONS SECTION

JUN 07 1373

NRØ19 CG PLAIN

TELETYPE

7:54 PM URGENT 6-/7-73 RWR

TO ACTING DIRECTOR (149-10024)

FROM CHICAGO (149-1060) 2P

CRASH OF UNITED AIRLINES FLIGHT 553, BOEING 737, CHICAGO, ILLINOING, Ecroley
12-8-72. DAMV. 00: CHICAGO.

RE CHICAGO TEL JUNE 6 LAST AND BU PHONE CALL TO CHICAGO THIS DATE.

SA ROBERT E. HARTZ PROCEEDED TO MIDWAY TOWER SHORTLY AFTER CRASH OF UNITED FLIGHT 553. HE WAS DISPATCHED TO MIDWAY TOWER AS A LOGICAL INVESTIGATI STEP TO DETERMINE IF THERE WAS A POSSIBLE VIOLATION OF THE DAMV STATUTE CONCERNED WITH THE UNITED AIRLINE ON ARRIVING AT THE TOWER, SA HARTZ IDENTIFIED HIM-FLIGHT CRASH. SELF AS AN FBI AGENT AND EXPLAINED THE REASON FOR HIS PRESENCE. HE WAS INVITED BY THE CHIEF FAA REPRESENTATIVE AT THE TOWER AND BY MR. FAA REGIONAL HEADQUARTERS, CHICAGO, TO LISTEN TO THE RECORDING MADE IN THE TOWER OF THE CONVERSATION HELD BY THE TOWER WITH UNITED AIRLINES FLIGHT AT NO TIME DID SA HARTZ REQUEST TO BE ALLOWED TO LISTEN TO THE TAPES. AFTER LISTENING TO THE TAPES. SA HARTZ IDENTIFIED A SOUND AS BEING THAT OF THE STALL INDICATOR ON THE AIRCRAFT. END PAGE ONE

Mr. Cenmy

My

Mr. Eardley

Mrs. Hogun

Mr. Felt ___ Mr. Baker

Mr. Callahan Mr. Cleveland

Mr. Ge

Mr. Jenkins ____ Mr. Marshall __ Mr. Miller, E.S. Mr. Sovers ___

Mr. Thempson.

Mr. Welters ... Tele Boom _

Mr. Boise _ Mr. Bornes .

Mr. Czemeten

b6 b7С

-8

JUN 20 1973

SPIAN S 2 IAN

PAGE TWO

FAA PERSONNEL AGREED THAT SA HARTZ WAS RIGHT AND IMMEDIATELY

NOTIFIED FAA HEADQUARTERS IN WASHINGTON.

THE RESULTS OF THE CHICAGO FBI INVESTIGATION WERE TURNED OVER TO MR. OF NTSB ON DECEMBER 11, 1972. MR. WAS MOST PROFUSE IN HIS THANKS TO THE FBI FOR THIS ASSISTANCE

IN THIS INVESTIGATION.

E ND

b6 b7C

!emorandum

TO

FROM

R. F. Bate

SUBJECT: CRASH OF UNITED AIR LINES FLIGHT 553, CHICAGO, ILLINOIS 12/8/72

DESTRUCTION OF AIRCRAFT OR

MOTOR VEHICLES

DATE: June 14, 1973

1 - Mr. Gebhardt

1 - Mr. Bates

1 - Mr.

1 - Mr.

1 - Mr. Thompson

1 - Mr. Bowers

b6 b7C

Mr. Mintz : Mr. Eardley Mrs. Hogan

Mr. Felt. Mr. Baker

Mr. Callal in Mr. Cleverand

Mr. Marshall Mr. Miller, E.S. Mr. Soyars _

Mr. Thompson

Mr. Walters _

Tele. Room Mr. Baise 🎉

Mr. Barper

Mr. Bower

Mr. Herington Mr. Conmy .

Reference is made to memorandum of Mr. Baise to Mr. Bowers, June 13, 1973, regarding captioned matter in which Mr. Ruckelshaus requested we review the files regarding aircraft crashes and determine if our investigation in above matter was the first time the FBI has interviewed witnesses before representatives of the National Transportation Safety Board (NTSB) arrived on the It is noted that Chairman John H. Reed, NTSB, both in his letter to Mr. Ruckelshaus, June 5, 1973, and in his testimony before the House Government Activities Subcommittee hearings regarding certification of light aircraft on June 13, 1973, stated the FBI's investigative activities in this particular case were unusual in that they interviewed witnesses and listened to tower tapes prior to NTSB having done so.

Upon receipt of Mr. Reed's letter of June 5, 1973, we promptly reviewed approximately 80 aircraft crash files dating back to 1960 for the express purpose of determining whether or not captioned case was the first incident where FBI Agents interviewed surviving witnesses, including flight attendants, prior to NTSB's We also attempted, through a review of those files, to arrival. determine if this case was the only one in which FBI representatives listened to the tower tapes prior to NTSB having done so. unable to establish those facts from our files because the time element regarding our interviews has heretofore never been questioned. It is the unspecified recollection of some FBI Headquarters personnel familiar with aircraft crash matters that we have previously interviewed witnesses prior to NTSE5 REC. 15, 149-10024

It is and has been, as pointed out in our letter Mr. Reed of June 11, 1973, the FBI's policy to respond to these emergencies as quickly as possible to determine if a violation within our investigative jurisdiction exists and to render all possible assistance to NTSB, including the services of our disaster team. In some instances FBI Agents have responded to aircraft crashes immediately via helicopter, as we did in the crash of Eastern Airlines Flight 401 in the Florida Everglades William Florida, on

Enc. - Sant 6-19-73

NSI:jyl (7)

PERS REC. VINETE CONTINUED - OVER

Memorandum to Mr. Gebhardt
Re: CRASH OF UAL FLIGHT 553,
CHICAGO, ILLINOIS, 12/8/72

December 29, 1972. In one specific incident concerning the crash of Alaska Airlines Flight 1866 near Juneau, Alaska, on September 4, 1971, NTSB representatives reached the crash scene two days following the actual crash. In the meanwhile, the FBI was conducting investigation and rendering whatever assistance possible concerning the identification of the victims. NTSB representatives have previously advised the Bureau due to the limited number of their regional offices and small number of employees, it is difficult for them to respond as quickly as does the FBI to the scene of an aircraft crash.

As a practical matter, aircraft crashes are/deemed to be caused by factors other than criminal actions, such as mechanical failure or pilot error, and our field office representatives on the scene terminate their investigative efforts once the cause of the crash has been determined, generally by the Federal Aviation Administration or NTSB. Our field offices do not as a matter of policy advise Bureau Headquarters whether or not our investigation and interviews are conducted prior to the arrival of NTSB. However, if it is deemed desirable by Mr. Ruckelshaus, we could canvass a selected number of our field offices who have handled aircraft crashes within their Division to determine if investigative personnel there recall specifically whether or not the FBI has previously interviewed witnesses prior to NTSB representatives having done so.

ACTION:

None. For information.

M

M

manufacture and the second sec	the state of the s
Routing Slip	3
FD-4 (Rev. 19.22.69)	Date 6-5-73
To: Director	
Att.:	- FILE
1 7	Title UNITED AIRLINES
SAC SAC	Title UNITED FIRMES
	-
ASAC	
☐ Supv.	SPECIAL MAND CARRY
Agent	- SPECIAL - HAND CARRY
SE SE	
	RE:
CC	!
Steno	
Clerk	_ Rotor #:
ACTI	
Acknowledge	Open Case
Assign Reassign Reassign	Prepare lead cards
☐ Bring file ☐ Call me	Prepare tickler Return assignment card
Correct	Return file
Deadline	Search and return
Deadline passed	See me / 119 - 100 24
Delinquent	Serial # NOT RECORDED
Discontinue	Post Recharge Return
Expedite	Send to 10 JUN 13 1973
File	Submit new charge out
For information	Jubilit report by
Handle	Туре
Initial & return	al De
Return with explanation or nota	ution as to action taken.
iteratii wiiti explanation of horo	
Per conversation h	oetween Bureau Supervisor
JOHN ADAMS and KEN	GRANT of Chicago, enclosed
are xerox copies of	of all material made available
to NTSB concerning	United 553 Crash.
M. area of	SAC R. G. HELD
Mile Local Control	CHI CAGO
See reverse ATT	Office
See reverse (STORIGHA)	
ı. ^E	PO: 1972 472-390/10

9

= 4/

149- ENGLOSURE 24-

- 149-10024-

FEDERAL BUREAU OF INVESTIGATION

	Dote of transcription December 9, 1972
1	
	Mrs.
Mrs. United A	Virginia, telephone was interviewed was interviewed to the constant was interviewed was a stewardess for advised she is currently employed as a stewardess for times (UAL), based in Washington, D.C. and has been used for approximately years.
Washingt	On December 8, 1972, she advised she was assigned as edess in the coach section of UAL flight 553, departing con, D.C. at Omaha, Nebraska with one stop at Chicago, concerning the UAL flight 553 of December 8, 1972, furnished the following information:
flight edidentitico-pilot them and cof the coton and compared to the section to the secti	Mrs. advised that the UAL crew assigned to flight December 8, 1972, was composed of the captain, co-pilot, engineer, and three stewardesses, including herself. The les of the members of the cockpit crew, that is the captait, and flight engineer are unknown although she recognized is confident that she has flown with them as a member crew on previous occasions. She stated that in addition elf, two other stewardesses were assigned to this flight, whose first name is known to her only as and a third stewardess, the confident of the flight in question and she, Mrs. assisted as a stewardess in the first-class for the flight in question and she, Mrs. assisted as a stewardess in the coach section. Both have been employed by UAL as stewardesses for a of years.
D.C. Natshe pers	Mrs. advised that the flight crew had a schedule the check-in time for flight 553, which was to depart Washi at light Airport at 1:40 PM that day. She estimated that sonally arrived at the airport at approximately 12:30 PM and that Mrs. arrived at the same time.
aircraft	Mrs. stated that in accordance with airline re, it is normal for the flight crew to board the departite about 30 minutes before departure time. She stated that recollection she boarded the aircraft with the other
s ROBERT J?	Chicago, Illinois. DOLAN, N. ROBERTS, JR.: MAH Dote dictated Dote dictated
document co	entains neither recommendations nor conclusions of the FBI ty of the FBI and is loaned to your agency; it and its to be distributed outside your agency, nor duplicated


two stewardesses assigned at about 1:10 PM on the day in question.
Mrs. stated that flight 553 of December 8, 1972, was assigned
to a Boeing 737 aircraft. As they boarded the plane, she recalled
that they were aware that the flight engineer was then aboard
since his flight bag was observed. It is the usual procedure
that the flight engineer boards early to run his instrument checks.
Mrs. stated that after the stewardesses had boarded the
aircraft, the flight engineer made a tour of the airplane as is
normal procedure before passenger boarding. She stated that while
she is not personally acquainted with the flight engineer, he
is known to her as
b7
Other than the three stewardesses and no other
individuals were aboard the airplane in question at that time.
The stewardesses commenced to discharge the various duties assigned
them before passengers are boarded. Normally the duties assigned
to stewardesses at this time, Mrs. stated includes such
things as checking oxygen equipment, over-head racks, seating
area; etc. These were the things that the three stewardesses
on flight 553 did at this time. She explained that she personally
walked to the rear of the aircraft and entered the restroom to
insure it was properly equipped for the flight. Mrs.
stated that this inspection of the interior of the aircraft by
the stewardesses revealed nothing of an unusual nature was present
in the airplane.

Before boarding passengers, the catering staff brought food aboard the airplane, which procedure was normal in every respect. In addition to the stewardesses and catering personnel, the only other individual to board before the passengers was a Passenger Service Agent from UAL who advised concerning certain passengers that were to be preboarded. While aboard the aircraft the Passenger Service Agent, as is his custom, made a visual inspection of the cabin area.

Airline personnel at approximately this time brought an invalid passenger aboard the airplane by means of a fork-lift truck. Mrs. stated that the boarding of this passenger was handled by Mrs. and she knew little of the details be concerning that passenger. She stated she could describe her b7C only as an elderly Negro woman wearing a neck brace and carrying

3 CG 149-

a cane. While Mrs tended to the boarding of this pas- senger, she, Mrs continued with her preboarding duties.
senger, she, Mrs. continued with her preboarding duties.
In addition to the invalid woman brought aboard, a woman and her
infant son were also boarded in advance of regular passengers.
This woman, she stated, was assigned to the first row of the
coach section. Although she could not identify her by name.
Mrs. described this woman as a white female in her
approximately in height, attired in a green pant-
suit. She carried a white totebag. This passenger was ticketed
to Omaha, Nebraska. She had a green backpack. Her infant son,
she recalled, wore yellow booties. Airline personnel later brought
a board a box containing clothing for the baby which included a
fuzzy orange baby nightgown. Mrs. stated that a family
of six was then boarded, whom she could not fully identify. This boarded
family consisted of a mother, father, and four children, the
children consisting of and The ages of the
children ran from to years and she stated she recalled
there were "two odd and two even". She related that she learned
the children were ages and Mrs.
described the father as very slender, age approximately
medium height, hair. He was attired in a blue shirt, dark
pants, and wore no suitcoat. She had no recollection of luggage
carried. The mother, she stated, was also slightly built, approx-
imately years of age, with hair, and attired in a rust
colored sweater and slacks. Mrs. stated that she talked
with these children during the course of the flight and during
conversations recalled one of the girls mentioning Germany and
commenting in this regard that she, the little girl, had her hair
cut short while in Germany. Mrs. had the impression that
this occurrence was approximately one year ago.
Mrs. stated that other than those previously
mentioned, she had no specific recollection of other passengers b7c
aboard flight 553.
Concerning the number of passengers aboard this flight,
Mrs. explained it was normal procedure for a passenger
count to be made prior to departure of the flight. She stated
that she and Mrs. took an actual head count of those
passengers assigned to the coach section of the airplane, while
Mrs. counted those passengers in the first-class



·	
Mrs. explained that she and Mrs. noted	•
what appeared to be a drag on the engines and then what she des-	
cribed as a "surge of power" and an elevation of the aircraft's	
nose. There was no suggestion of a problem she said and it was	
her impression that they had overshot the runway and were going	
around for another approach. She became aware that the liquor	
drawer had begun spilling out bottles of liquor at this point and	
glasses fell to the floor strewing fragments of glass about the	b6
cabin area. Miss stated that she recalls a number of	b70
"popping noises" and minor flashes, which reminded her of light	2,
bulbs breaking. At this time Mrs stated that she was	
going to open the door of the aircraft. believing they had	
landed. It was her impression Mrs stated that the aircraft	
was still airborne and cautioned against opening the door. It	
was then that she noted that the cabin area of the plane had	
collapsed and Mrsrushed to the door on the left side	
of the aircraft, opened it and found the exterior of the aircraft	
in flame. Mrs. closed the door and the two of them rushed	
to the emergency exit on the right side of the airplane and im-	
mediately opened the door. Mrs. said that she had no	
conscious recollection of getting out of her seat, but was aware	
that she was on her feet and knew that something terrible had	
happened. She said the only thing she recalled was that she had	
to get the passengers out of the aircraft and that together she	
and Mrs. sought out the survivors and began moving	
them out of the plane. They first assisted, she said, an uniden-	•
tified woman passenger through the exit and noted that the pas-	
senger fell some distance to the ground. Mrs. at this	
point then released the emergency escape chute so that other	b 6
passengers reaving the affectate would not be injured. Together	b70
she and Mrs assisted all available passengers to the ground and were later informed that they had helped approximately	2,0
15 persons to escape the aircraft. Once they had assisted all visible passengers, she and Mrs. were forced to abandon	
the aircraft because of the intense smoke. Mrs. stated	
that she did not observe fire in their section of the aircraft.	
Once she and Mrs. had cleared the aircraft, they were	
assisted by authorities and immediately taken to Holy Cross	
Hospital for emergency treatment.	
than but an all an all as an interest to a second at	

commented that in reconsidering all events relating to the flight of UAL flight 553 on December 8, 1972, s he noted nothing in anyway that would be considered of an unusual nature prior to the time of the actual crash. She commented that she had neither heard nor observed anything on the part of any b6 person aboard that flight which in anyway could she consider Further Mrs. stated there was nothing of an b7C unusual nature regarding the operation of the crash itself or procedures followed before the actual crash. Mrs. she could recall nothing of an additional nature concerning the a ircraft passengers or activities relating to the flight in question which would provide additional information regarding the cause of the accident in question.

149-10024-

CG 149-1060 JSR:jeo 1

) ·		
The	following investigate t Chicago, Illinois:	ation was cond	lucted by SA	
on December 8	following individual ection with the crast, 1972, however, were f value concerning i	on of the Unit	Ad Aim Ti	ber 9, plane
	Mr. and Mrs.			•
	Mrs.	•		
· · · · · · · · · · · · · · · · · · ·	Mrs.	_		ь6 ь7С
-	Mr.]]		
	Mr.	- - -	·	
	Mr. and Mrs.			
,	Mr.		*;,	
	Mr.			+
	Mrs.		* *	ь6 ь7С
	Mrs.		, y	
· v	Mrs.			
	Mr. and Mrs.	1	· •	
*			Searching 1060	7-10

Moderal

7P3

Mr.	- 1		
Mr.		*	
Mr.			ь6 ь7с
Mr.			
Mr.			
	20	adv.	risad

Miss age advised that on December 8, 1972, at approximately 2:30 in the afternoon, she was walking east on 71st Street from Pulaski and when she was approximately half-way between Haml... and Avers Avenues, she saw a plane going in a northerly direction. The plane was very low, almost at roof-top level. When she first saw the plane, it appeared to her to be flying over Ridgeway Avenue about 7100 South and it continued north disappearing from her sight. She said she does not recall hearing the plane's motors and she heard no explosion and saw no signs of fire or explosion while the plane was in the air.

Mrs. advised that sometime between 2 and 3 o'clock on the afternoon of December 8, 1972, she was sitting in the front room of her house facing east and saw a plane flying slightly above roof-top level going in a northerly direction and it appeared to be flying above Ridgeway Avenue. She said the plane seemed as if it was gliding and she did not hear the sound of the motors. When she saw the plane in the air, it was completely intact and there was nothing to indicate that a fire or explosion had occurred aboard.

b6 b7С

Mr. advised that on the afternoon of December 8, 1972, between 2:20 and 2:25 in the afternoon, he was sitting in the livingroom of his home looking out the window and he observed an airplane flying very low slightly above roof-top level. The plane appeared to be flying over the houses between Ridgeway and Hamlin Avenues. He said the plane appeared to be gliding as he could not hear the plane's motors. At the time he saw the plane, it was completely intact and there was no evidence of a fire or explosion aboard the plane.

Mrs. advised that around 2:30 on the afternoon of December 8, 1972, she was in her home looking in an easterly direction out the front window and saw a plane flying in a northerly direction over Ridgeway Avenue at about roof-top level. She said she heard the faint sound of motors and at the time she saw the plane, there was nothing to indicate that a fire or explosion had occurred aboard. She said that she did not hear the sound of the plane crashing but moments later she saw smoke and flames.

b6 b7C

Queen of the Universe School, advised that around 2:30 p.m. on the afternoon of December 9, 1972, she was on the second floor of the school which is located in the 7100 block of South Hamlin Avenue. She said she heard the sound of a plane and it sounded as if it was on top of the building and she ran to the window. She looked out in an easterly direction and saw only the tail portion of the plane north of 71st Street disappearing from her view. She did not see the entire plane while it was still in the air.

149-10024-

FD-3024Rev. 71-27-70)

FEDERAL BUREAU OF INVESTIGATION

	•
Date of transcription 12/11/72	
On December 8, 1972,	
turned over to	
Special Agents (SA) and JOHN H.	
WILMES, at 6:20 p.m., one voice recorder which	
had obtained from the wreckage of United Airlines	
Boeing 737, number N9031U, flight 553. The recorder	
was tagged and turned over to	
Air Safety Investigator, National Transportation	
Safety Board, at 6:35 p.m.	

Interviewed	on	12/8/72	W Ch	icago,	Illinois	File	# CG 149-1060 -5
		ЈОНИ Н	\				
L	and			RA	C/les	Date dict	12/11/72
ьу			7			Date dict	ultu

ь6 ь7с

b6 b7C CG 149-1060 WJM:jeo

On December 9, 1972, the following people were contacted regarding the crash of United Air Lines Flight 553 in the vicinity of 70th and Lawndale Avenue, Chicago, Illinois. This neighborhood investigation revealed nothing of a positive nature. The following people were contacted:

ь6 ь7с

Rufile 149-10024

Please Je Att.

Rec. From clinero 6-6-73 HSiv 6 80.

Sacrated B

ь6 ь7с

FEDERAL BUREAU OF INVESTIGATION

ъ6 b7С

b6 b7С

	Date of transcription 12/9/72
	Illinois, was interviewed at his residence.
	He stated that instant United Air Lines (UAL) flight left from Gate Number 24, National Airport at Washington, D.C., on schedule. He noted that electronic equipment for searching passengers and baggage was present at Gate 24; however, it was not used at the time instant flight was boarded.
	He stated the flight from Washington, D.C. to Chicag was completely uneventful and he slept most of the way. Prior to scheduled arrival time, the pilot announced that the plane was flying at 4000 feet, was over Gary, Indiana, and would land at Chicago momentarily.
	He said the cloud cover was rather heavy and that when the aircraft broke through the cloud cover, he thought it was flying too low. He pointed out that he is an experienced air traveler, flying throughout the United States twice a month. He stated that to the best of his knowledge, this was the only landing approach the aircraft made and that it had not been waived off prior to the time of impact. He said he was occupying Seat He estimates this is approximately to the of the passenger compartment. He said the nearest emergency exit was over Seat 7A, He pointed out that both seats on the pilot's compartment.
· '	He stated that he noted absolutely nothing unusual until immediately prior to impact. He said that at the very last moment, the engines revved up, the nose of the ship came up, the tail went down. Immediately thereafter, there was a tremendous crash and the aircraft's electrical systems went out. He said he had his seat belt fastened and he, as well as the others, did also because the passengers had been so instructed by the flight crew in preparation for landing.
rviewed on	SA JOHN M. MC DONOUGH JMM/kpr Dote dictated CG 149-/060.//
f the I gency;	cument contains neither recommendations nor conclusions FBI. It is the property of the FBI and is loaned to your it and its contents are not to be distributed outside

He said that he believed he "blacked out", but he does not know for how long. The next thing he recalls is stumbling forward in the aircraft and along with what he believes to be two other passengers, he tried to open the emergency door over what he believes to have been Seat 7A. He and these two other passengers succeeded in opening the exit door and were immediately met with a of flames. They thereupon shut the emergency door at which time he noticed light coming from the rear of the aircraft. He then heard what he believed to have been a stewardess say words to the effect, "You can get out this way". He thereupon moved to the rear of the aircraft and successfully exited same. When he stepped from the aircraft, he believes he was standing on the cement foundation of a building. His first recollection thereafter, is to the effect that fire and police vehicles were on the scene and from this he must have "blacked out" for at least a few minutes.considering the fact that it would have taken emergency police and fire vehicles at least five to ten minutes to reach the scene.

He was then taken to Holy Cross Hospital, Chicago, for treatment, where he was treated and released.

He concluded that he noted absolutely nothing unusual prior to the time of impact other than the engines revving up, the nose of the ship coming up, and the tail of the ship going down immediately prior to the point of impact. He concluded that he noted absolutely nothing of an unusual nature prior to the crash.

The following description was obtained through observation and interrogation on December 9, 1972:

Name:	- 1	
Sex:	Male	
Race:	White	
Date of Birth:	•	
Place of Birth:		
Residence:		
Home Phone Number:		
Marital Status:	Married	

b6 b7С 3 CG 149

Employment:		
	10 West 35th Street Chicago, Illinois	b6
Business Phone Number	extension	b70

FEDERAL BUREAU OF INVESTIGATION

	Dat	e of transcription December 9,]	1972
1	9.5		*
		p.*	
7111	nois, telephone number	was interviewed:	at his
	ce, Ch	icago, Illinois. Mr.	
advi	sed he was a passenger abo		UAL) flight
553	from Washington, D.C. to C	hicago, Illinois, on Do	ecember 8,
1972	. He also advised that he	: is	
info 553	was interviewed in corrmation he might furnish at Chicago, Illinois on De	nection with any observegarding the crash of ecember 8, 1972.	UAL flight
000		- , - :	
	He said that as he r	ecalls, he was sitting	in seat
	located in the		of the ai:
craf	t. He said he observed no	thing unusual or extra	ordinary
rega	rding this flight up until	tne time the flight w	as approachi
Chic	ago's Midway Airport. Jus	st prior to arriving at	cnicago,
the	captain of the aircraft specified the flight was a little	lote but the t there wou	Id he arrivi
that	the flight was a little b Chicag <u>o's Midway</u> Airport in	late, but that they wou	nutes At
at C	time stated he lo	ooked out of the window	of the air-
0 20 4	t and noticed that there	was a heavy for cover a	nd that he
Was	not able to see any ground	d or anything else outs	ide of the
airo	eraft window. He said that	t he was aware that the	plane was
desc	ending into the Midway ap	proach pattern and from	his obser-
vati	ons, thought that possibly	y the flaps were not ex	tended outwa
and	down as far as he has pre-	viously observed the po	sition of
fla	os on other flights he has	taken.	
	All of a sudden, Mr	realized that	the aircraf
had	full power applied and al	most immediately the pl	ane seemed
to	drop directly towards the	ground and then bellied	l. He said
t ha	t as the plane started to	drop, he realized or th	ought that
the	would probably crash so	he placed his head as f	ar down be-
twe	en his knees as possible.	Immediately after the	plane had
c om	e to a rest he got out of	his seat, to assist the	two steward
w ho	were attempting to open o	ne of the rear doors of	the aircrai
AS	the three of them were ablothe cabin area so they c	e to open this door, in	tely. They
1 nto	n went to the other side o	f the aircraft and one	ely. They and the other
tne	r and one of the stewardes	ses activated the escar	ne slide chut
He He	recalls that approximately	eight to ten passenger	s. all from
	— · · · · · · · · · · · · · · · · · · ·		
wed on 12	/8/72 of Chicago, Illi	nois File # CG 149-	- 1000-17
242	THOMAS H. GREENE and		
ana	THOMAS H. GREENE AND FING/M	AH 12/9	3/72
	1 hr10/m	AH Date distated 12/5	

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency, nor duplicated within your agency.

rear part of the aircraft, disembarked via the slide chute and
he was then ordered out of the aircraft himself by one of the
stewardesses.
Mr. said he does not recall looking up to the
forward part of the aircraft cabin so therefore could furnish no
information as to what the situation looked like further forward.
He said he heard no unusual noises or any other unusual activity
aboard the aircraft other than what he has already described
and characterized the two stewardesses in the rear of the aircraft
as being extremely calm, efficient, and highly couragous.
as being extremely calm, ellicient, and highly couragous.
Hoon loowing the simplest he said he was taken aloun
Upon leaving the aircraft, he said he was taken along
with another passenger, name unknown, by chicago police unit
to holy cross hospital where he was entered for treatment.
advised that he did not feel that he had been seriously
injured in anyway. He was able to make contact with
from his office who had previously arranged to meet him
at Midway Airport and he departed Holy Cross Hospital, coming
directly to his place of employment at
The state of the s
stated that in the crash he lost

FEDERAL BUREAU OF INVESTIGATION

	1 Dote of transcription December 9, 1972	
		o.
<i>e</i> 1	Mrs.	
	Maryland, telephone	
	was interviewed at Holy Cross Hospital,	
	2701 West 68th Street, Chicago, Illinois. She advised	
	she is currently employed as a stewardess for United	b6
	Air Lines (UAL) based in Washington, D. C., and has	b70
	been so employed for years. Mrs. stated	
	that on December 8, 1972, she was assigned as a	
	stewardess in the coach section of UAL Flight 553	
	departing Washington, D. C. for Omaha, Nebraska with	
·	an intermediate stop at Midway Airport, Chicago,	
	Illinois. She furnished the following information	
	regarding the flight of UAL Flight 553 on December 8,	
	1972:	
	Mrs. advised that the UAL crew	
	assigned to Flight 553 for December 8, 1972 was composed	
	of the captain, co-pilot, flight engineer, and three	
	stewardesses, including herself. The identities of	
	the members of the cockpit crew, that is the captain,	
•	co-pilot and flight engineer are unknown, although she	
	recognized them and is confident she has flown with	b6
	them as a member of the crew on previous occasions.	b70
	She stated that in addition to herself, two other	
•	stewardesses were assigned to this flight, a Mrs.	
	whose first name is known to her only as	
•	and a third stewardess, These	
	stewardesses are also based in Washington, D. C. Mrs.	
	added that was assigned as	
	stewardess in the first class section for the flight in	
	question and Mrs. assisted Mrs. as a	
	stewardess in the coach section. Both and	1 .
	have been employed by UAL as stewardesses for a number]
	of years.	
	Mag adviced that the flight owns had	
	Mrs. advised that the flight crew had	
	a scheduled 12:40 PM check in time for Flight 553 which	
	was to depart Washington, D. C. National Airport at	
	1:40 PM that day. She estimated that she personally	
	arrived at the airport at approximately 12:30 PM and she	
	7)	-
nterviewed o	12/8/72 of Chicago, Illinois File # CG 149- 1060-13	
		- b
	SAS ROBERT J.//DOLAN, and JOHN/W. ROBERTS/catd 12/9/72	b

noted that Mrs. arrived at that same time. She explained that it is normal procedure to board the aircraft: 30 minutes before departure time and she estimated that she boarded the aircraft designated for Flight 553 at about 1:10 PM that day. She said that the airplane in question was a Boeing 737 type. stated that all three stewardesses boarded the aircraft together and as she did so she noted that the only individual then aboard the aircraft was the flight engineer who was then making his instrument checks in the cockpit area. She stated they then commenced to perform the various duties assigned them prior to boarding passengers. She noted in this regard that she checked the overhead racks, oxygen equipment and seating areas in the forward section of the coach compartment. She noted that additional magazines were needed and later told the Passenger Service Agent who brought aboard additional magazines. stated that as a result of the inspection of the aircraft she was certain that no one was aboard the airplane at that time other than authorized personnel. Nothing of an unusual nature occurred during the pre-boarding operation, nor was anything of an unusual nature observed. Following the boarding of the stewardessed she said catering personnel brought food aboard the aircraft for the flight. A Passenger Service Agent, whose identity is not known to her, but who is familiar to Mrs. boarded the aircraft as is the usual procedure prior to boarding passengers. The stewardesses were informed they had two groups to be pre-boarded before the regular passengers were admitted. At this time Mrs. informed the Passenger Service Agent regarding the supply of magazines and he later returned to the aircraft with those magazines.

At approximately this time airline personnel boarded a passenger on a fork lift truck. Mrs. stated she did not know the identity of the passenger, but described her as an elderly Negro woman, wearing a neck brace and carrying a cane who informed her that she had just won a ten year injury suit against the Post Office Department. This woman was from Chicago, Illinois. In addition a woman passenger and her small

b6 b7C

b6 b7С


b6 b7C son were pre-boarded. She stated that this woman and her son were assigned seats 6A or 7A in the first row of the coach section. She described the woman passenger as white, approximately 25 years in age, 5'4" to 5'5" tall, and having dark hair. She estimated that the child was approximately six to eight months in age.

Mrs. stated that a family was next
boarded consisting of a mother, father and four children.
She stated that the children consisted of one boy age
and three girls. The oldest was a girl age whose
first name was All of the children had light
hair. She described the father as slim, very small
in stature, approximately in height, years
of age, sandy hair, and wearing a blue shirt and dark
pants. The mother was approximately years of age,
tall, slight build, sandy hair, and wore
a brown sweater and slacks. Mrs. stated that
she recalls the mother leaving the aircraft later on
that day following the <u>crash in</u> the company of the
oldest daughter. Mrs. was asked if there was
anyone aboard this flight that was known to her and
she recalled a woman and two children whose name she
recalls was She recognized these people as
having previously flown with her. Mrs. had a
young child three to five years of age who was a ticketed
passenger and carried an infant approximately one year
old who was not ticketed or on the manifest. It was
Mrs. recollection that she saw Mrs.
the child, and the infant leave the plane after the
crash in Chicago. One other group aboard the aircraft
was recalled by Mrs. which group consisted of a
mother, a daughter, husband of the daughter, and another
relative of the family named the latter she
believes survived the crash. She stated this group
was assigned to seats 15B, 15C, 15D and that was
assigned to seat 16B.
T.,
In addition to the above, Mrs. stated
she recalls no other passengers aboard the aircraft nor
any details regarding the passengers which might aid

in their identification.

b6 b7C

> b6 b7C



ь6 ь7с

> b6 b7C

Normally, during the landing procedures when the "seat belt" light goes on the stewardesses pass up and down the aisles insuring the belts are fastened and that cigarettes are extinguished, and they all make a visual check to insure that carry-on luggage In regard to the flight in question, Mrs. is secure. stated the normal procedures were followed with the exception that the "seat belt" light had been on because of weather conditions. Both she and Mrs. made the visual check, returned to their seats, fastened their seat belts and prepared for the landing of the airplane. She stated that she estimated it may have been two minutes before the aircraft actually touched down and she recalled she and Mrs. sat there talking. Up to this point she noted nothing out of the ordinary was heard or observed.

After a short lapse of time she stated they noted what she described as a "drag on the engine" and then a "surge of power." It was her impression she recalled that the pilot may have missed his approach and was gaining altitude for another approach. stated she then had the sensation that the aircraft had stopped and was tilted. She indicated to Mrs. that she was going to open the door and Mrs. immediately objected stating she thought they were still in flight. Mrs. stated that she had no experience of impact although both she and Mrs. immediately noticed the buffet was tilted forward and the contents therein were falling to the floow. then noted that the cabin part of the aircraft seemed to be collapsed whereupon she rushed to the emergency exit door on the left side of the aircraft and opened it only to find the aircraft on the outside aflame. flames were in the immediate area of the door and singed When this occurred she immediately closed the her hair. emergency exit. In the brief instant that these events occurred she was aware of the complete disarry of the passenger coach compartment recalling that seats had tumbled onto the passengers and the overhead racks and items had spilled down over the passengers. She also

b6 b7C

> b6 b7С

vividly recalled that the year old boy who was	
a member of the family of six was under the seats	
on the floor around seat number 16 and was apparently	
dead. At this point Mrs. stated she and Mrs.	
went to the emergency exit on the right side of	
the aircraft and opened it. They assisted an un-	
identified female passenger through the exit only to	
realize in doing so the passenger had fallen some	
distance. In an effort to avoid injury to the other	b6
	b 70
passengers they then released the escape shoot to fill	
the hole where the woman had fallen. After doing so	
she and Mrsassisted the passengers who had	
survived the crash to evacuate the aircraft. She	
stated they were later told that they had helped	
approximately 15 passengers to leave the aircraft.	
After assisting those passengers who had survived she	
and Mrs. were then forced to leave the aircraft	
because of the intense and overpowering smoke in the	
cabin. There was no fire detected in that section of	
the airplane at the time they left. Once they had	
reached the ground and moved from the airplane they	
were assisted by area residents who had come to the	
scene. Authorities then provided she and Mrs.	
transportation to Holy Cross Hospital where they have	
remained since.	
Mrs. stated that in reviewing events	
relating to the flight of UAL 553 on December 8, 1972,	
she noted nothing of an unusual nature in any way until	
the time of the actual crash itself. She stated that	
she neither heard nor observed anything on the part of	b6
any person aboard the airplane which she considered	b7C
irregular. She noted that there was nothing of an un-	D/C
usual nature noted or observed regarding the operation	
of the aircraft itself until the time of the crash. There	
was no explosion of any kind noted by her. Mrs.	
stated she could recall no additional information regarding	
the passengers, the aircraft itself, or the activities	
of the flight in question which would aid in providing	
additional information regarding the cause of the crash	
itself.	

149-10024-

PASSENGERS ON UNITED FLIGHT 552 DECEMBER 8, 1972

Mrs. residence telephone Wheelchair patient	b6
Mr. Chicago	b 70
Mr. Going from Washington to Omaha Possible phone or number for Richardson Travel Residence,]
Mr. Washington to Omaha Reservations through Du Pont International Travel	-1-
Mr.	
Mr. R. BLADGETT Going on to Omaha Booked through Omaha Reservations	· · · · · · · · · · · · · · · · · · ·
Ginnell Travel and Transportation Business 402-348-4618 Travel and Transportation 402-344-4877	
Mr. Air Travel Transportation Card Number Block account	b6 b7С
Miss Washington residence Traveling on Air Travel Card Number Block account	
Congressman GEORGE COLLINS Congressman from State of Illinois 149-1060-8 SEARCHED_INDEXED_SERIALIZED_B_FILED_B JAN 3 1973	
FBI CHICAGO	1

Mr. F.L. ELLISON Washington residence	8)()
American Express Card Wheelchair patient	
Washington residence American Express Card	ь6 b7с
Mr. Omaha business phone Residence Booked through Richardson Travel Agency	
Mr. Omaha business phone Booked through Travel and Transportation Agency 344-4877 by	
Miss Washington residence, Harrington Hotel, Room 305 Wheelchair passenger	
Mr. Chicago residence Washington contact number Booked through Tally Columbia American Express Number	b6 b7С
Miss C. HEWITT Chicago phone number 312-353-3864 Traveling on government travel request number A9132068	
Mrs. D. HUNT Washington residence 301-299-3785	
Mr. Washington business number Residence, Maryland	
Mrs. Washington residence Going on to Omaha Mrs. had infant named	b6 b7C

Mr. H. JORDAN Going to Midway Washington phone number 588-1585 Traveling with Mr. H. JORDAN, same phone Mr. R. KNOWLAND Business phone Washington 821-3131 Using Air Travel Plan Card AAP51682 Official of Glenair Incorporated of Glendale, California Going to Omaha, Flight 146A, December 7, 1972 Mr. Phone| b6 b7C Doctor A. KRILL Chicago residence 312-667-6251 Traveling on Bank of America Credit Card Number 4673090191636 Mr. Going to Omaha Omaha business phone number Booked through travel and transportation of Omaha 402-345-3300 Reservationist named Mr. Going to Midway Air travel plan card number American Block Account Mr. Going to Midway **b**6 Booked through Madison Bank Travel Department b7C Chicago, Illinois Mr. Going to Midway Mr. Washington Mayflower Hotel Room 585 Traveling on Air Travel Card Block Account

Mrs.				
Chicago r	esidence		7	•
•	n residence		T ·	
_	merican Expi			
Miss Chicago r	esidence on residence	. •	7	-
Charged A	merican Exp	ress		
Miss	<u></u>	-		-
Chicago r	esidence,			
Local con	tact			
Washingto	n contact	l F	Room 401	
Air Trave	l Plan			
Amarican	Bar Associat	tion Rloca	Z Account	

ь6 ь7с

- 4 -

WALT PATTERSON booked on to Omaha	
Omaha business phone 402-341-2904	
ticket booked through T & T Travel Agency, Harney Street,	
402-345-3300, by girl named	
Miss	b6
Washington residence	b7C
Room 401 Chicago phone	
Chicago contact	
Mr	
Washington business phone 659-6649, paid for ticket by Air Travel Plan card	
Mr	
Chicago business phone 312-585-7800, Ext.	
	b6
Mr	b7C
Chicago business phone 312-353-3680, Residence traveling	
under	
Mr.	
Chicago residence phone 312-798-8625,	
previous telephone contact girl	
called in was	
Wr.	
Chicago residence	
business 312-378-1000, ext.	
Sister	b6
Triple A	b7C
Maryland, Washington contact	
Ext.	
Mrs. traveling under book of American Credit Card	
Washington or Miami contact traveling with infant (s	ex
unknown) and year old daughter.	

Mr.		
booked on to Omaha	•	b6
Nebraska business phone 475-3361		ь7С
residence		
* * *	4	
Mr. J. WEST		
booked on to Omaha,		
Omaha business 341-1041, residence 391-2791,		
Washington contact 347-9550, ext. 607		
Group of 6 came in from Nairobi, Kenya, Africa, on Pan	Am,	
all with initial "W". One is woman.		
Mrs.		
business phone 312-842-4850		
booked through U-Travel, Inc., Chicago,		
telephone 312-667-3900, handled through		
Mr.		
address Nebraska		
booked on to Omaha,		
Omaha business 475-3361		
residence	•	b6
.,		b7С
Mr.		
residence possible		
business phone 312-654-3220		
The second secon		
Mr.		
Virginia		

FEDERAL BUREAU OF INVESTIGATION

	one flight recorder by Special A JR., the Office of Federal Burea which was obtained from Flight 5 had crashed in Chicago, Illinois	u of investigation (FBI), 53, United Airlines, which
	Mr. signed a	receipt for the recorder.
•		2 2 8
•		
	*	
	ها لله المراجع في المراجع المر	·
	- 8-	
•		* *

FEDERAL BUREAU OF INVESTIGATION


telephone number was interviewed at his residence by Special Agents who were identified to him as Special Agents of the FBI. He was advised that the FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.		
telephone number was interviewed at his residence by Special Agents and who were identified to him as Special Agents of the FBI. He was advised that the FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. (3) United Flight 553 reported he was on the approach but not yet at the outer marker.	1	
telephone number was interviewed at his residence by Special Agents and who were identified to him as Special Agents of the FBI. He was advised that the FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. (3) United Flight 553 reported he was on the approach but not yet at the outer marker.		
Interviewed at his residence by Special Agents who were identified to him as Special Agents of the FBI. He was advised that the FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up 0'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.		
who were identified to him as Special Agents of the FBI. He was advised that the FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	•	telephone number was
FBI is conducting an investigation regarding the air crash of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.		and who were identified to
of a United Air Lines 737 jet aircraft on this date. He was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listenin to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	him as S	pecial Agents of the FBI. He was advised that the
was further advised that he was being contacted regarding his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	FBI is c	onducting an investigation regarding the air crash
his interview by BOB SANDERS of WBBM Radio, Chicago, Illinois concerning his monitoring of a shortwave radio transmission between Midway Tower and two aircraft, the United Flight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. (3) United Flight 553 reported he was on the approach but not yet at the outer marker.	was furt	her advised that he was being contacted regarding
between Midway Tower and two aircraft, the United Fight 553 and a private Business Jet just prior to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	his inte	rview by BOB SANDERS of WBBM Radio, Chicago, Illinois,
He stated he frequently listens to the crash of the United aircraft. He furnished the following information: He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	hotwoon	Midway Tower and two aircraft, the United Flight
He stated he frequently listens to the radio transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. Stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	553 and	a private Business Jet just prior to the crash of the
transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. Istated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-1/1	United a	ircraft. He furnished the following information:
transmission between the Midway Airport Control Tower and approaching aircraft, and had been listening on this date at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. Istated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-1/1		He stated he frequently listens to the radio
at his residence since approximately 10:00 a.m. He stated he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up 0'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	transmis	sion between the Midway Airport Control Tower and
he was listening to Ross-5-band portable radio on frequency 118.7 on the aircraft frequency radio band. He was asked if he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	approach	ing aircraft, and had been listening on this date
118.7 on the aircraft frequency radio band. He was asked II he was positive that it was Midway Tower that he was listening to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-1/	ho was 1	istering to Ross-5-hand portable radio on frequency
to, to which he replied that he was positive, that he could not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-11 SA Line CG 149-1060-11	118 7 on	the aircraft frequency radio band. He was asked it
not pick up O'Hare from his residence. He stated that as he was listening he heard the following sequence of radio transmissions: (1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-11 SA United Flight 553 reported he was on the approach but not yet at the outer marker.	to . to 1	hich he replied that he was positive, that he could
(1) A Business Jet, believed it was a Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-11 SA Line CG 149-1060-11	not nick	un O'Hare from his residence. He stated that as ne
Sabre Liner, reported the outer marker. stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. Chicago, Illinois SA SA Vilb 12/9/72	was list	ening he heard the following sequence of radio
Sabre Liner, reported the outer marker. Stated that outer marker is located in the vicinity of 87th and Kedzie Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-11 SA Vilb 12/9/72	or answer	
outer marker is located in the vicinity of 87th and Redzle Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. CG 149-1060-11 SA	Cabua I	
Avenue.) Midway Tower cleared this aircraft to land on Runway Number 31 Left. (2) United Flight 553 reported he was on the approach but not yet at the outer marker. Chicago, Illinois SA Villy (2) United Flight 553 reported he was on the approach but not yet at the outer marker.	outer ma	rker is located in the vicinity of 87th and Redzie
(2) United Flight 553 reported he was on the approach but not yet at the outer marker. Con 12/8/72 of Chicago, Illinois File # CG 149-1060-1/	Avenue.)	Midway Tower cleared this aircraft to land on
approach but not yet at the outer marker. 20 12/8/72 Chicago, Illinois File # CG 149-1060-1/	nullway 1	
SA Chicago, Illinois File # CG 149-1060-1/		
SA	approaci	but not yet at the outer marker.
SA		
SA		
SA	12/8/	72 Chicago, Illinois CG 149-1060-11
Vilb 12/9/72	On	
381	SA	

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency, nor duplicated within your agency.

CG 149-
(3) Midway Tower responded to United Flight 553 and requested that they report outer marker.
(4) next heard Midway Tower advise the Business Jet to disregard, make a left turn to 190 degrees, climb out to an altitude of 2500 feet and contact Chicago Approach. stated United Flight 553 still had not reported the outer marker at this time.
(5) Business Jet again reported outer marker and was again cleared to land on Runway Number 31 Left.
/(6) Ten to fifteen seconds later United Flight 553 reported outer marker in Kedzie inbound.
(7) Midway Tower informed United Flight 553 he was number two to land - number two in sequence.
(8) Midway Tower asked Business Jet what was air speed. The reply from Business Jet was 120 knots.
(9) Midway Tower asked Business Jet if he had the left runway in sight. Business Jet responded, "Yes."
(10) Business Jet was then asked by Midway Tower if he had Runway Number 31 Right in sight. Business Jet replied again, "Yes."
(11) Midway Tower began to tell Business Jet to change landing to Runway Number 31 Right. According to this transmission was stopped at which point Midway Tower advised the Business Jet, "Correction, you are still clear to land on 31 Left."
(12) Midway Tower advised United Flight 553 to cut his approach, make a left turn to 180 degrees, and climb to an altitude of 2500 feet. According to Midway Tower did not advise United Flight 553 to contact any other frequency.
(13) Midway Tower contacted United Flight 553 and asked if they understood the last transmission stated that he did not hear a reply from United Flight 553.

b6 b7C

ь6 ь7с



obtained	The following is a des through observation and]
× .	Race Sex	White Male	b6 b70
	Date of birth Place of birth Height	Six feet	
	Weight Hair	pounds	
	Eyes Occupation	He is a student at	
· ·	Residence	Resides with his paren	nts.

1emorandum

TO.

FROM

Mr. Baise

W.

6/13/73 DATE:

REFERENCE TO FBI'S INVESTIGATION SUBJECT: REFERENCE TO FEE UNITED AIRLINES FLIGHT 553 CRASH,

CHICAGO, ILLINOIS, 12/8/72, AT HEARINGS OF HOUSE GOVERNMENT ACTIVITIES SUBCOMMITTEE

6/13/73

Mr. Paker Mr. Callahan Mr. Cleveland Mr. Conrad . Mr. Gebhardt Mr. Jenkins . Mr. Marshall Mr. Miller, E.S. € Mr. Soyars . Mr. Thompson Mr. Walters . Tele. Room Mr. Baise . Mr. Barnes Mr. Bowers _ Mr. Herington Mr. Conmy. Mr. Mintz. Mr. Eardley _

Mrs. Hogan

Mr. Felt.

A story in the Washington Post, page A-17, 6/13/73, indicated that the questions raised by the National Transportation Safety Board (NTSB), concerning FBI investigation of captioned crash, would probably be discussed at the House Government Activities Subcommittee hearing on Federal Aviation Administration (FAA) certification of Light Aircraft today, 6/13/73. The story made reference to a letter from NTSB Chairman John H. Reed to Mr. Ruckelshaus dated 6/5/73, and Mr. Ruckelshaus' reply dated 6/11/73.

To insure that the FBI's position in this matter would be $_{
m b7C}^{
m BS}$ fully protected, if the subject arose at the hearing, I (Bowers) Administrative Assistant to Congressman John contacted Buchanan (R.- Ala.) the ranking minority member of the Subcommittee. He was given a brief rundown on the questions raised by Mr. Reed and the responses given by the FBI in the letters. SA Fulton, Congressional Services Office, went by Congressman Buchanan's office prior to the hearing and made copies of both letters available to who furnished them to Congressman Buchanan who was absent at the time. In retrospect, this was a valuable asset to our cause, as when the matter arose at the subsequent hearing, it was obvious that Buchanan had also briefed other minority members on this matter as they were prepared to question Reed most effectively and to put the matter in the proper perspective

The hearing convened at 10 a.m., 6/13/73, and Mr. Reed was the first witness. SA Fulton was present. Reed made no reference to the United Airlines crash in his prepared statement. After a few brief questions relating to contents of the statement, Subcommittee Chairman Jack Brooks (D.-Tex.) mentioned the "Post" article and asked Mr. Reed to comment on the NTSB's concern in the FBI's role at the crash scene. Reed repeated basically the same questions he raised in the letter to Mr. Ruckelshaus and emphasized

1 - Mr. Gebhardt - Enc.

1 - Mr. Fletcher Thompson - Enc.

1 - Mr. Mintz - Enc.

2 Jun 2 11973

(CONTINUED

W Oo F 0 Copy

Unrecorded

Bowers to Baise (cont'd.)
Re: REFERENCE TO FBI'S INVESTIGATION, UNITED AIRLINES
FLIGHT 553 CRASH

that based on the Board's experience, the FBI's action in questioning witnesses and listening to the recording between the tower and the pilot was unusual.* Chairman Brooks then made the point that "having 50 FBI Agents standing by to rush to the crash scene" disturbed him somewhat and wondered if this were true at all airports throughout the country. He mentioned this would be an exorbitant waste of manpower. At this point Congressman Buchanan pointed out that it was not surprising to him in the least that 50 FBI Agents would respond to a major commercial plane crash scene in Chicago in view of the number of Agents assigned to that city, plus the ever present possibility of FBI jurisdiction as indicated by Mr. Ruckelshaus' letter. Congressman Robert P. Hanrahan (R.-Ill.) mentioned that he had just missed this flight by some 2 hours and that he personally was not the least concerned about the FBI's investigation of the Aside from the sabotage angle, Congressman Hanrahan pointed out that a U.S. Congressman was aboard and was killed in the crash -(Congressman George W. Collins, D.- Ill.). Hanrahan then pressed Reed to determine if this were the first time he could recall that the FBI had interviewed witnesses before members of the NTSB arrived on the scene. Reed replied that to the best of his recollection this is true but he could not state it as a fact.

Congressman Stanford E. Parris (R.-Va.) then took up the questioning. He raised the point as to the pertinency of the line of inquiry. He indicated it was obvious the FBI acted in good faith and was attempting to resolve whether there were any violations under its jurisdiction and that the subject was not related to the over-all purpose of the hearing. Chairman Brooks responded that he felt the matter was germane to the Subcommittee's interest in transportation safety, particularly if the FBI's actions had in any way interfered with the responsibilities of NTSB. Chairman Brooks then commented, "We had plenty of trouble with Ruckelshaus while he was over at Environmental Protection Agency and now we are having more trouble." Congressmen Buchanan, Hanrahan and Parris would not let up on Reed and finally made him admit that the FBI had every right to take the action it took in this matter and that in any event, because of the past excellent relations between the two agencies, this would have been an isolated misunderstanding and had actually not affected the discharge of responsibilities of either agency. They were joined in the concluding questioning by Congressman Andrew J. Hinshaw (R.-Calif.) who got the point across that the FBI could not be expected to stand around and wait until NTSB members arrived before taking necessary

^{*}Both letters were read into the record.(CONTINUED - OVER)

Bowers to Baise (cont'd.)
Re: REFERENCE TO FBI'S INVESTIGATION, UNITED AIRLINES
FLIGHT 553 CRASH

action. Congressman Buchanan further exposed the nebulous nature of NTSB's complaint by observing that if an explosion had caused the crash, the FBI by listening to the tape, would have been aware of this and the over-all investigation under the sabotage statute would have fallen to the FBI. Reed admitted this would have been true.

A copy of the transcript of the hearing relating to this particular matter will be obtained when available.

RECOMMENDATION:

That the attached letter to Congressman Buchanan expressing our appreciation be approved and sent.

Enclosure

UNITED STATES GERNMENT

Memorandum

то

Mr. Bowers

DATE: June 13, 1973

FROM

Gary Baise

SUBJECT:

CRASH OF UNITED AIRLINES FLIGHT 553

5010-106

\$

Mr. Ruckelshaus has reviewed the memorandum and has requested that we review the files and determine if this is the first time the FBI has interviewed witnesses before members of the NTSB arrived on the scene. Mr. Ruckelshaus would like to know if Mr. Reed's recollection is correct.

GB:EDM (3)

Cotato otato

Die 2021

NEC-15
149-10024

2 Jun **21**]1973

CSO. Dura

59 JUN 291973 539 Mr. Walters ______
Tele. Room _____
Mr. Baise _____
Mr. Barnes _____
Mr. Bowers ____
Mr. Herington _____
Mr. Conmy ____
Mr. Mintz ____
Mr. Eardley ____
Mrs. Hogan _____

Mr. Felt Mr. Baker

Mr. Callahan Mr. Cleveland Mr. Conrad __ Mr. Gebhardt _

Mr. Jenkins

Mr. Marshall __ Mr. Miller, E.S. Mr. Soyars ___ Mr. Thompson .

149-10024-1

Mr. John H. Reed

Chairman

National Transportation Safety Board

Department of Transportation

Washington, D. C. 20591

Dear Mr. Reed:

Your letter dated June 5, 1973, concerning the FBI's investigation into the crash of a United Air Lines Boeing 737 at Midway Airport, Chicago, Illinois, on December 8, 1972, has been received.

The FBI has primary investigative jurisdiction in connection with the Destruction of Aircraft or Motor Wehicles (DAMV) Statute, Title 18, Section 32, U. S. Code, which pertains to the willful damaging, destroying or isabling of any civil aircraft in interstate, overseas or foreign air commerce. In addition, Congress specifically designated the FBI to handle investigations under the Crime Aboard Aircraft (CAA) Statute, Title 49, Section 1472, t. S. Code, pertaining, among other things, to aircraft iracy, interference with flight crew members and certain Specified crimes aboard aircraft in flight, including assault. murder, manslaughter and attempts to commit murder or manslaughter.

PBI investigation of the December 8, 1972, Unite Air Lines crash was instituted to determine if a violation of the DAMV or CAA Statutes had occurred and for no other The fact that Mrs. E. Howard Hunt was aboard the plane was unknown to the FBI at the time our investigation was instituted.

It has been longstanding FBI policy to? immediately proceed to the scene of an airplane crash for the purpose of developing any information indicating a possible Federal violation within the investigative jurisdiction of the FBI. In all such instances liaison

> NOTE: See Bates to Gebhardt memo,

RFB: kap

b7C

June 11, 1973

- Mr. Thompson

1 - Mr. Gebhardt - Mr. Bates

- Mr.

1 - Mr. Mintz

b6 b7C

Mr. Baker Mr. Callahan Mr. Cleveland Mr. Gebhardt Mr. Jenkins Mr. Marshall Mr. Miller, E.S. _ Mr. Soyars _ Mr. Thompson ... Mr. Walters -Tele. Room Mr. Baise _

Mr. Barnes Mr. Bowers Mr. Herington . Mr. Conmy ... r. Mintz r. Eardley

rs. Hogan

MAIL ROOM

TEMETYPE UNIT

Mr. John H. Reed

is immediately established with the National Transportation Safety Board (NTSB) personnel upon their arrival at the scene.

Approximately 50 FBI Agents responded to the crash scene, the first ones arriving within 45 minutes of the crash. FBI Agents did interview witnesses to the crash, including flight attendants. Special Agent (SA) Robert E. Hartz proceeded to the Midway Airport tower shortly after the crash to determine if tower personnel could shed any light as to the reason for the crash. On arriving at the tower, SA Hartz identified himself as an FBI Agent and explained the reason for his presence. He was invited by Federal Aviation Administration (FAA) personnel at the tower to listen to the recording made at the tower of the conversation between the tower and United Air Lines Flight 553. At no time did SA Hartz request to be allowed to listen to the tapes. listening to the tapes, SA Hartz identified a sound as being that of the stall indicator on the aircraft. The FAA agreed that SA Hartz was right and immediately notified FAA Headquarters at Washington, D. C.

The FBI's investigation in this matter was terminated within 20 hours of the accident and on December 11, 1972, Mr. William L. Lamb, NTSB, was furnished with copies of the complete FBI investigation pertaining to this crash after it was determined there was apparently no violation of the DAMV or CAA Statutes.

In order to avoid the possibility of any misunderstanding concerning our respective agencies' responsibilities and to insure continued effective liaison between the NTSB and the FBI, I have designated SA Richard F. Bates, Section Chief, Criminal Section, General Investigative Division, FBI Headquarters, Washington, D. C., telephone number 324-2281, to represent the FBI concerning any matters of mutual interest.

Sincerely yours,

William D. Ruckelshaus

William D. Ruckelshaus Acting Director

- 1 The Deputy Attorney General
- l = Assistant Attorney General Criminal Division

federal bureau of investigation COMMUNICATIONS SECTION

NRO13 CG PLAIN

555 PM URGENT 6-14-73 RWR

TO ACTING DIRECTOR (149-10024)

FROM CHICAGO (149-1060) 2P

DAMV.

12-8-72.

Mr. Call
Mr. Cleveland
Mr. Conrad
Mr. Geb! ardt
Mr. Jenkins
Mr. Marshall

Mr. Felt

Mr. Bake

Mr. Conmy _____
Mr. Mintz _____
Mr. Eardley ____
Mrs. Hogan ____

b6

b7C

RE CHICAGO TELS 6-6 AND 7-73.

CHICAGO.

00:

FOR INFO OF BUREAU, NTSB CALLED A HEARING AT THE SHERATONO'HARE MOTEL NEAR O'HARE FIELD SOLELY FOR THE PURPOSE OF HEARING
TESTIMONY ON THE PART OF SHERMAN SKOLNICK. THIS HEARING WAS CALLED
AT REQUEST OF UNITED AIRLINES INASMUCH AS SKOLNICK HAD MADE MANY
ACCUSATIONS ACCUSING UNITED AIRLINES, COLUMBIA BROADCASTING SYSTEM,
FEDERAL AVIATION ADMINISTRATION AND THE JUSTICE DEPARTMENT OF BEING
IMPLICATED IN AN ALLEGED COVERUP OF THE CRASH OF UNITED AIRLINES
FLIGHT 553.

THE HEARING WAS CONVENED JUNE 13, 1973, AND IS CONTINUING
THROUGH 6-14. SKOLNICK HAS MADE SEVERAL RIDICULOUIS ACCUSATIONS
CONCERNING THE FBI, ONE OF WHICH WAS THAT 100 FBI AGENTS WERE STAKED
OUT IN THE NEIGHBORHOOD OF THE CRASH BECAUSE THEY HAD BEEN
ADVISED BEFOREHAND THAT THE AIRPLANE WAS GOING TO CRASH. 149-10034
SKOLNICK HAS ACCUSED FBI AGENTS OF REMOVING TWO MILLION DOLLARS
FROM THE AIRCRAFT. HE HAS ALLEGED THAT MANY OF THE PASSENGERY 21 1973
ABOARD THE AIRCRAFT DIED OF CYANIDE POISONING. HE HAS ATTEMPTED
TO CONNECT THE CRASH OF UNITED AIRLINES WITH THE WATERGATE
INVESTIGATION DECAUSE OF THE FACT THAT THE WIFE OF E.
HOWARD HUNT WAS ABOARD THE AIRCRAFT AND WAS KILLED.

TE PERS. REC. UNITE

UNIRECORDED COPY I

END PAGE ONE

PAGE TWO

ALSO LINKED CRASH TO A PIPELINE LOBBY, INVESTMENT SCANDALS IN SWITZERLAND, LEGISLATIVE ACTS IN COSTA RICA AND UNDERWORLD DEALINGS IN STOLEN CURRENCY.

THE CHICAGO OFFICE HAS HAD NO OBSERVER PRESENT AT THESE HEARINGS AND DOES NOT INTEND TO. UNITED AIRLINES SECURITY PERSONNEL HAVE KEPT THIS OFFICE ADVISED OF SKOLNICK'S TESTIMONY.

THE NEWS MEDIA IN THE CHICAGO AREA HAVE BEEN GIVING COVERAGE
TO THE HEARING BUT HAVE INDICATED THAT SKOLNICK'S TESTIMONY AND
THE TESTIMONY OF THE WITNESSES HE CALLED HAS BEEN COMPLETELY
UNSUBSTANTIATED. ACCORDING TO PRESS REPORTS PERSONS
IN ATTENDANCE SNICKERED THROUGHOUT SKOLNICK'S TESTIMONY.
UNITED AIRLINES SECURITY PERSONNEL HAVE ADVISED
THAT EVERYTHING THAT SKOLNICK HAS STATED CONCERNING THE CRASH
HAS NOT BEEN SUBSTANTIATED AND IS OBVIOUSLY A FIGMENT OF SKOLNICK'S
IMAGINATION.

THIS INFO BEING FURNISHED TO BUREAU BECAUSE OF THE NEWS COVERAGE OF THE HEARING AND THE POSSIBILITY BUREAU MAY RECEIVE INQUIRIES.

END

HOLD

Iemorandum

Mr. Gebh TO

R. F. Bales

MOTOR VEHICLES

SUBJECT:

FROM

CRASH OF UNITED AIR LINES FLIGHT 553 BOEING 737 CHICAGO, ILLINOIS DECEMBER 8, 1972 DESTRUCTION OF AIRCRAFT OR DATE: 6/8/73

1 - Mr. Gebhardt.

Mr. Bates

Thompson

- Mr. Mintz

Mr. Walters Tele. Room . Mr. Baise - h7C Mr. Barnes Mr. Bowers Mr. Herington . Mr. Conmy Mr. Mintz _ Mr. Eardley Mrs. Hogan

Mr. Baker

Mr. Callahan Mr. Cleveland Mr. Conrad Mr. Jenkins

Mr. Marshall Mr. Miller, E.S. Mr. Soyars .

Mr. Thompson

Captioned plane crashed at Midway Airport, Chicago, Illinois, 12/8/72. Our Chicago Agents immediately responded within 45 minutes of the crash and for approximately 20 hours conducted investigation, including interviews of witnesses and survivors. An Agent also reviewed the airport tower tape of communications between the tower and victim Some of this was done prior to the arrival of the National Transportation Safety Board (NTSB) representatives on the scene. One of our pilot-trained Agents recognized the signal on the tower tape as being emitted by the stall speed indicator on the plane signifying the pilot had lost speed Weather conditions were not good since it was and crashed. snowing at the time and visibility was approximately one mile.

Forty-five people died in the crash, including Mrs. E. Howard Hunt (wife of Watergate figure) and U. S. Congressman George Collins of Chicago, Illinois. Two of the deceased victims were on the ground. The FBT Disaster Squad identified 12 of the crash victims through fingerprints. were 18 survivors.

According to the Federal Aviation Administration (FAA) on the scene there was no evidence developed to indicate a violation within the investigative jurisdiction of the FBI and consequently our investigation was terminated and the results of our interviews and investigation were furnished in writing to NTSB on 12/11/72.

By letter dated 6/5/73, NTSB questioned the FBI's early response stating our investigation was both unusual and nontypical and that our Agents interviewed witnesses to the

Enclosure - Sent 6-11-73

Memorandum Bates to Gebhardt RE: CRASH OF UNITED AIR LINES FLIGHT 553

crash, including flight attendants, prior to NTSB interviews of those people. Additionally, NTSB also questioned the fact that an FBI Agent went to the control tower at Midway Airport and listened to tower tapes prior to NTSB having done so. Our Chicago Office advised that the Agent who reviewed the tower tapes did so at the invitation of an FAA representative on the scene. To us, these were logical investigative steps to determine if a violation within our jurisdiction was present.

We are not aware of any previous problem with NTSB and our relations with them have been excellent. Section Chief Richard F. Bates and Number One Man Newell S. Irwin met with representatives of NTSB at their request on 5/25/73, at which time our mutual responsibilities in aircraft accident matters were discussed. NTSB representatives did not appear to be keenly aware of the FBI's interest and jurisdiction in Destruction of Aircraft or Motor Vehicles (DAMV) matters which was explained to them in detail. At that meeting, Air Safety Investigator, who was on the scene at the Midway crash, raised questions relating to the coordination of NTSB and FBI investigations in aircraft accidents. He stated that often FBI Agents were on the scene prior to NTSB representatives due to the limited number of NTSB personnel throughout the country. It would appear, therefore, that NTSB's prime concern is the quick response and early investigation by our Agents at crash scenes prior to the arrival of NTSB personnel which could possibly result in and infringement upon the investigative responsibility of NTSB.

Our Chicago Office has advised that they worked very closely with NTSB on the scene at this accident and personally expressed his thanks for the FBI's assistance and investigation in this case. This has been coordinated with Mr. Mintz, Office of Legal Counsel.

ACTION: It is recommended that the attached letter be forwarded to NTSB in response to their inquiry explaining the FBI's interest and jurisdiction concerning aircraft crashes.

wal

g^Mg

The spe

por Not

A5

b7C

Mr. Felt Mr. Baker Mr. Callahan Mr. Cleveland Mr. Conrad \(\text{\text{\text{\text{\text{\text{d}}}}} \) April 25, 1973 Mr. Gebhardt Mr. Jerkins Mr. Marshall Mr. Miller, E.S. __b7C Mr. Soyars _ of UPI called and said that they Mr. Thompson would be running a story in which the National Transportation Mr. Walters Safety Board had alleged that the FBI interjected itself into Tele. Room the investigation of the United airline crash at Chicago on Mr. Kinley -12/8/72 without invitation. She said that she was only checking Mr. Armstrong the Bureau's position on this and had nothing to do with the basic Mr. Bowers Mr. Herisigton story which was being written by another UPI writer. Ms. Herwig Mr. Mihtz I told her that if there was evidence that a case came Mrs. Neenan within our jurisdiction under the Destruction of Aircraft Statute, we would investigate and that we would not require anybody's invitation since it was our responsibility. I advised her further that in this case the preliminary and subsequent facts failed to indicate sabotage as had been publicly revealed and that we conducted no investigation. I told her also that our Disaster Squad assisted in identifying victims in most airline crashes and that we had done so in this situation, and I advised her further that that is done on invitation by some appropriate official. She subsequently called me back and wanted to know who had invited us in connection with this case and after checking I advised her that we had received a request to help with the fingerprint identification of the victims from James B. Conlisk, Jr., Superintendent of Police, Chicago, Illinois, and that he had the concurrence of an United Airline Vice President. (Dr. George Kidera, who was not identified to her by name.) It is to be noted that we also conducted some investigation in connection with the money being carried by Mrs. Howard Hunt who died in this crash and who was the wife of one of the Watergate subjects; however, that investigation could not be construed as investigation of the crash. Our Disaster crew identified 12 victims through fingerprint identification and their activities were limited to that purpose. 1 - Mr. Thompson 1 - Mr. Gebhardt Jack Herington AY 197 DRIGINAL FILED IN 58 MAY 1619 NOT RECORDED 178 MAY 11 1973

September 7, 1973 1 -- Mr. Gebhardt 1 - Mr. Bates 1 - Mr. Mr. John H. Reed Chairman National Transportation Safety Board b6 Department of Transportation b7C Washington, D. C. 20591 O UNITED BURGES Dear Mr. Reed: Your letter dated August 31, 1973, and its have been enclosures forwarded to me by received. My General Investigative Division staff has carefully reviewed the new procedures concerning National Transportation Safety Board - Federal Bureau of Investigation Interface in Aircraft Accident Investigation. We are in complete agreement with them. The Special Agent in Charge of each of our Field Divisions is being furnished copies of the items you submitted to us. You may be assured of the full cooperation of the FBI in all matters of mutual interest relating to our combined statutory responsibilities. Sincerely yours.

B. M. Kelley 40 / 49 / 00 24 Clarence M. Kelley 14 SEP 11 1973 Director JKH/DEF RY/N SEE NOTE PAGE 2. JKH:sls (5) \$IS.

TELETYPE UNIT

Assoc. Dir.
Asst. Dir.:
Admin.
Comp. Syst.
Files & Cont

Ident.

Inspection
Intell.
Laboratory
Plan: & Eval.
Spec. Inv.
Training
Legal Coun.
Cong. Serv.
Corr. & Crm.
Research
Press Off.
Telephone Rm.

Mr. John H. Reed

By letter dated 6/5/73, Mr. Reed raised issue regarding our immediate preliminary investigation into the accidental crash of United Air Lines Flight 553 in bad weather at Chicago, Illinois, on 12/8/72. Reed inquired as to the FBI's listening to the tower tapes and interview of some witnesses prior to arrival of National Transportation Safety Board (NTSB) investigators. The implication was that such activity could interfere with NTSB investigative responsibilities. Subsequent communication with NTSB by General Investigative Division personnel indicates NTSB was unfamiliar with the FBI's investigative responsibilities under the Crime Aboard Aircraft and Destruction of Aircraft or Motor Vehicle Statutes. By letter 6/11/73, to Mr. Reed, our responsibilities were fully explained and as a result of that letter and subsequent communications, a proposed interface was developed. forth our mutual investigative responsibilities with NTSB; directs NTSB investigative personnel to cooperate fully with the FBI on the scene, and provides for a mutual exchange of pertinent investigative data.

The foregoing letter is to acknowledge our agreement with the proposed interface.

An airtel is being prepared to furnish all SACs copies of the interface, directory of NTSB field supervisors, and map showing NTSB field offices. (Sufficient copies of map were furnished by NTSB).

February 1, 1974

EX-103

15 45 149-10024 17

Honorable Jerry Litton House of Representatives Washington, D. C. 20515

Dear Congressman Litton:

Your communication of January 24th enclosing correspondence from your constituent, Mr. been received.

The FBI has primary investigative jurisdiction in connection with the Destruction of Aircraft or Motor Vehicles (DAMV) Statute, Title 18, Section 32, U. S. Code, which pertains to the willful damaging, destroying or disabling of any civil aircraft in interstate, overseas or foreign air commerce. In addition, Congress specifically designated the FBI to handle investigations under the Crime Aboard Aircraft (CAA) Statute, Title 49, Section 1472, U. S. Code, pertaining, among other things, to aircraft piracy, interference with flight crew members and certain specified crimes aboard aircraft in flight, including assault, murder, manulaughter and attempts to commit murder or manslaughter.

FBI investigation of the December 8, 1972, United Air Lines crash was instituted to determine if a violation of the DAMV or CAA Statutes had occurred and for me other reason. The fact that Mrs. E. Howard Hunt was aboard the plane was unknown to the FBI at the time our investigation was instituted

-It has been longstanding FBI policy to immediately proceed to the scene of an airplane crash for the purpose of developing any information indicating a possible scheral

1 - Kansas City - Enclosures (3)

1 - Congressional Services - Enclosures (3) RCD:cmc (7) CONTINUED PAGE TWO amo

b6

b7C

b6

FEB

Assoc. Dir. Asst. Dir.:

Admin. Comp. Syst. _

Ext. Affairs

Inspection Intell.

Laboratory Plan. & Eval. __ Spec. Inv. .

violation within the investigative jurisdiction of the FBI. In all such instances liaison is immediately established with the National Transportation Safety Board (NTSB) personnel upon their arrival at the scene.

Approximately 50 FBI Agents responded to the crash scene, the first ones arriving within 45 minutes of the crash. FBI Agents did interview witnesses to the crash, including flight attendants. A Special Agent proceeded to the Midway Airport tower shortly after the crash to determine if tower personnel could shed any light as to the reason for the crash. On arriving at the tower, he identified himself as an FBI Agent and explained the reason for his presence. He was invited by Federal Aviation Administration (FAA) personnel at the tower to listen to the recording made at the tower of the conversation between the tower and United Air Lines Flight 553. At no time did this Agent request to be allowed to listen to the tapes. After listening to the tapes, the Agent identified a sound as being that of the stall indicator on the aircraft. The FAA agreed that the Agent was right and immediately notified FAA Headquarters in Washington, D. C.

The FEI's inve	stigation in this	matter was terminated
within 20 hours of the a	ccident and on Dec	sember 11, 1972,
		with copies of the
complete FBI investigati	on pertaining to	this crash after it
was determined there was	apparently no vic	plation of the DAMV
or CAA Statutes. /		

b6 b7C

I trust the above information will satisfactorily explain the facts in this case.

Sincerely yours,

G. M. Kelley

Clarence M. Kelley Director

NOTE: We have had prior consituent correspondence with Congressman Litton (D-Mo). Bufiles contain no derogatory information regarding ______ The article enclosed by ______ presents a distorted view of a magazine article by "American Opinion" concerning our investigation of the crash of United Air Lines Flight 553, Chicago, Illinois, 12/8/72 on which Mrs. E. Howard Hunt (wife of the Watergate figure) was on board. Bufile 149-10024.

NOTE CONTINUED PAGE THREE

Honorable Jerry Litton

The article quotes information developed by Sherman H. Skolnick who is well known to the Bureau with respect to his inquiries in this case. The above response paraphrases our letter of 6/11/73 to Mr. John H. Reed, Chairman of the National Transportation Safety Board, Department of Transportation, Washington, D. C., which factually portrays our jurisdiction and subsequent investigation of this crash. Reply coordinated with the Special Crimes Unit of the General Investigative Division.

HOUSE OF REPRESENTATIVES, U.S. WASHINGTON, D.C. 1005 Longworth HOB

January-24,...., 19

Respectfully referred to

Congressional Liaison Department of Justice Federal Bureau of Investigation 9th Street & Penna. Ave., N. W.

Attached is excerpt from a magazine entitled Public Opinion [published at Belmont, Massachusetts 02178] relative to the plane crash in which E. Howard Hunt's wife was killed.

I would appreciate any comments you might be able to make concerning the allegations and assertions set forth in this article.

Presumably, Public Opinion magazine has some connection with the John Birch Society.

Very respectfully,

JL/BW

Assoc. Dir. Asst. Dir.: Admin. Gen. Inv. Ident. . Inspection ___ Intell. Laboratory ____ Plan. & Eval. Spec. Inv. Training ____ Legal Coun. Telephone Rm. ___ Director Sec'y

ь7С

REC- 45

Wang & Market and	
L. W. Co.	
	Missouri 64118

1 January 1974

The Honorable Jerry Litton House Post Office Washington D. C. 20515

My dear Congressmen,

Watergators John Birch Society.

Page 8 The Plane Crash

If this write up is correct, what may be done about it?

Do you think that the public should know?

	Sincerely	yours,
*		
,		

149=10024=17

the smoke cleared the Cuban patriots had been wiped out or captured, and Fidel Castro was more firmly than ever in control. The patriots had been promited air over, without which the operation could not have succeeded, but when they were already at sea the Kennedy Administration decided to withhold it. The planes never arrived, and the patriots were easy prey. Indeed, Castro was perfectly aware that the invasion was coming.

One of our informants who was actively involved in the Bay of Pigs recalls an interesting story told to him by the late David Ferrie. Who was also a C.I.A. agent, and who was one of those accused by New Orleans District Attorney Jim Garrison of having participated in the assassination of President Kennedy. According to Forrie, E. Howard Hunt went to Cuba several times before the Bay of Pigs, and personally explained the operation to Fidel Castro. Hunt also supervised the installation on the beaches of pointed, four-foot stakes to impede the invaders. And this of course would make Hunt's reputation as a "fanatic anti-Communist" rather dubious.

At also would go a long way toward a complete explanation of Watergate.

The Plane Crash

-On-December 8, 1972, Mrs. Dorothy Hunt, wife of C.I.A. man E. Howard Hunt, got aboard United Air Lines Flight 553 at National Airport, bound for Midway Airport in Chicago. Mrs. Hunt herself was a C.I.A. agent, and had been one even longer than her husband. They were a C.I.A. "family." Indeed, contrary to earlier denials from the White House, it now develops that Mrs. Hunt was the Watergate "bag woman." It was she who, pursuant to orders, delivered the offer of Executive Clemency to Watergate defendants. It was she who paid them off in return for their promises to keep their mouths shut. And on December 8, 1972, she apparently was travelling with about two million dollars in cash, traveller's

checks, and money orders which the Nixon Team had handed over to buy her lence. Mrs. Hunt was privy to the same atergate information as was her husband, and could have used it to blow the Watergators from the water.

Also on Flight 553, was C.B.S. network newswoman Michele Clark, who was getting ready to do a story on Watergate. There was also a man carrying a gun, and calling himself Harold R. Metcalf, who claimed to be an agent for the Bureau of Narcotics and Dangerous Drugs.

And there were Ralph Blodgett and James W. Krueger, attorneys for the Northern Natural Gas Company of Omaha, along with some others associated with them. Mr. Blodgett and the others were angry at John Mitchell - one of the most important of the accused Watergate conspirators - and were determined to blow the lid off the case. It seems that former Attorney General Mitchell, and his friends running the Justice Department, were putting the screws to Northern Natural Gas. On September 7, 1972, some officials of that firm and its subsidiaries were indicted on federal criminal charges in Omaha, Chicago, and Hammond, Indiana - and charged with bribing local officials to let a gas pipeline go through.

· All of this has been uncovered by Mr. Sherman H. Skolnick of Chicago, who is Chairman of the Citizens' Committee to Clean Up the Courts, and whose investigations have caused the departure of several corrupt Chicagoland judges. It was Skolnick who sent former Illinois Governor Otto Kerner to jail. And Skolnick reports that, to defend itself against the Justice Department's charges, Northern Natural Gas uncovered documents showing that Mitchell, while U.S. Attorney General in 1969, dropped anti-trust charges against its competitor, El Paso Natural Gas; that the decision was worth several hundred million dollars to El Paso — and that John Mitchell's law partner represented El Paso

AMERICAN OPINION

٠.

TVCLOSURE

149-10024-17

at the time. Indeed, says Skolnick, Mitchell mysteriously developed a stock interest in El Paso with a law partner as a nominee. And pipeline attorney Krueger was carrying the proof of all this on Flight 553, on his way back from Washington, where pipeline attorney Blodgett had been trying to get the charges against Northern Natural Gas dropped.

In other words, there were three different sources aboard United Air Lines Flight 553 who could have exposed various aspects of Watergate; Mrs. E. Howard Hunt, Miss Michele Clark, and the Northern Natural Gas crowd.

... As this aircraft approached Midway Airport, the outer marker, also known as the Kedzie Localizer - a signal which tells the pilot where he is - stopped working. So did the flight data recorder. So did the captain's altimeter, which records the plane's altitude. Indeed, circuit breakers started popping all over the place. And the weather was bad, so the pilot had no idea where he was. A witness on the ground says he was far off course. Eleven witnesses on the ground say the descending plane had no lights. And the chance of all this happening at the same time is about as likely as the possibility that Richard Nixon will ever make anything perfectly clear.

Indeed, a witness on the ground saw a descending parachute supporting an aluminum foil ball, which is a technique used to jam airborne navigational equipment. It is interesting to note that former White House counsel John Dean testified as follows before the Senate Watergate: Committee, about the sabotage plans of convicted Watergate boss G. Gordon Liddy: "When discussing the electronic surveillance, he said that he had consulted with one of the best authorities in the country, and his plan envisioned far more than bugging and tapping phones. He said that, under his plan, communications between ground facilities and aircraft could also be intercepted."

In other words, Flight 553 was apparently the victim of what the disarmament hoaxers call "massive overkill." But, believe it or not, there was even more. For instance, Air Traffic Control at Midway did not tell 553 that the Kedzie Localizer was not working. In fact it told the captain to continue inbound and land. Yet, at the same time, it told A.T.C. at nearby O'Hare Field that Flight 553 would circle Midway again. The confused pilot was given the idea that he was really in a holding pattern, when he was not. And the approach controller later testified that he had "forgotten" to issue approach clearance to Flight 553.

At 2:29 p.m., United Air Lines Flight 553 crashed in the streets just short of Midway Airport. Waiting for it on the ground were up to two hundred agents of Defense Intelligence and the F.B.I. which is interesting because F.B.I. regional headquarters is some twelve miles from the scene. The F.B.I. was there before the fire department, which responded within one minute of the crash. Apparently we are supposed to believe that the F.B.I. just happened to be holding a convention in the streets approaching Midway, when Flight 553 hit the ground. For some time after he revealed this incredible fact, Mr. Skolnick was called a liar. But in a letter dated June 11, 1973, to John H. Reed, Chairman of the National Transportation Safety Board, William D. Ruckelshaus, who at the time was Acting Director of the F.B.I., admits that in less than forty-five minutes after the crash about fifty F.B.I. agents were on the scene. Why? What were even fifty, let alone two hundred, F.B.I. agents there to do? Why were they present without being invited by the National Transportation Safety Board, as is customary? Did someone know Flight 553 was scheduled to crash? Were they at Midway Airport to arrest Mrs. Hunt, who had left Washington with about two million dollars in negotiable paper?...

Furthermore, the F.B.I. agents took

complete control of the crash site, refused to show their credentials, kept even the Chicago Police Department away from the scene, did the same to the Federal Aviation Administration, and stripped all the bodies of identification. So bizarre was the F.B.I.'s behavior that on June 5, 1973, Reed wrote Ruckelshaus for an explanation, recalling that "for the first time in the memory of our staff, an FBI agent went to the control tower and listened to the tower tapes before our investigators had done so; and for the first time to our knowledge, in connection with an aircraft accident, an FBI agent interviewed witnesses to the crash, including flight attendants on the aircraft prior to the NTSB interviews. As I am sure you can understand, these actions, particularly with respect to this flight on which Mrs. E. Howard Hunt was killed, have raised innumerable questions in the minds of those with legitimate interests in ascertaining the cause of this accident "

So the question once again arises: Has the F.B.I. been directed to suppress evidence which may well prove that the death of Mrs. Hunt — who could have exposed the entire Watergate mess — was not an accident, and that Flight 553 was sabotaged?

Furthermore, along these lines, it is also interesting to note that the last words we hear from the captain of Flight 553 - whose name, incredibly, was Wendell Whitehouse - were spoken at 2:26:24.66, according to the cockpit voice recorder, which apparently means that the co-pilot and second officer were flying the plane during the final 2½ minutes before the crash. The captain does not say a word during that long period of emergency! Indeed, the Chicago Tribune of March 25, 1973, reports that, according to the Cook County coroner's office, Captain Whitehouse was dead before Flight 553 ever hit the ground.

What killed Captain Wendell Whitehouse? In a report on the accident issued

by the National Transportation Safety rd, we learn that his body was found contain 3.9 micrograms per milliliter of cyanide - which just happens to be four times the amount necessary to kill him. Yet, the bodies of the co-pilot and the second officer contained no cyanide at all. We are told that the cyanide poisoning was the result of inhalation. after plastic foam burned in the fire, but the co-pilot and second officer were breathing the same air as Captain Whitehouse, so it appears that the captain was poisoned in some other way. In fact, the bodies of six of the Watergate-connected passengers had a cyanide content higher than they could have gotten from a so-called aircraft fire. And these were the only people in whom cyanide was found. Where then did the cyanide come from?

Your reporter doesn't know, but it is interesting to remember that among the passengers on Flight 553 was Harold R. Metcalf, who was carrying a gun, and who is supposed to be an agent for the Bureau of Narcotics and Dangerous Drugs. And an intelligence agent who managed to get to the crash site recalls that Metcalf has worked as a parachute jumper in Europe for the Central Intelligence Agency. Indeed, the agent recalls that when Metcalf stepped from the rear door of the hulk of Flight 553, he was wearing a jump suit - which is exactly what the well-dressed man wears if he expects the plane he is flying in to crash.

And soon after the crash, one of Skolnick's agents confronted Metcalf with the theory that the crash had deliberately been arranged; to which Metcalf blurted, "It wasn't supposed to" — and left the room. Could Metcalf have been what intelligence officers call a "double cutout," who was there to do a job, and didn't know that a job was supposed to be done on him?

It is also worth recording that the Administration kidnapped Alex J. Bottos, a Skolnick investigator, and kept him for forty days without charge in the Springfield, Missouri, federal hospital — the same place Robert Kennedy kept General Edwin Walker after kidnapping him — when Bottos tried to reveal that the two million dollars in negotiable paper Mrs. Hunt had carried on Flight 553 was being disposed of by a criminal "fence."

Finally, there is the incredible fact that on December 9, 1972 - exactly one day after the crash - White House aide Egil Krogh was appointed Undersecretary of Transportation. Krogh was of course one of the leaders of the so-called "plumbers" unit, which on behalf of Richard Nixon burglarized the offices of Daniel Ellsberg's psychiatrist. And as Undersecretary of Transportation he was in charge of the National Transportation Safety Board, which was supposed to be investigating the crash. Furthermore, on December 19, 1972, only eleven days after the crash, White House official Alexander P. Butterfield of Ervin Committee fame was appointed the new head of the F.A.A. - which was another agency supposed to be investigating the crash. And five weeks after the crash. Dwight Chapin, Richard Nixon's appointments secretary, who was also in charge of the so-called "department of dirty tricks," became a top official with United Air Lines.

All of this, of course, is crucially revealing, but notice that the kept national press and the Senate Watergate Committee have said not a word — which suggests they are participating in the coverup they so pompously denounce.

Bremer And The C.I.A.

As we have seen, the Watergate story is filled with fleeting mentions of the Central Intelligence Agency. James McCord was a C.I:A. agent for many years. So was E. Howard Hunt. And the C.I.A. gave Hunt whatever equipment he wanted to carry out his clandestine raids, from a wig to photographic equipment to false identification. Of course, we are constantly told that both Hunt and McCord had

"retired" prior to the Watergate burglary, but the question arises of whether the Agency would work so closely with people who were no longer on its payroll. Indeed, C.I.A. boss Richard Helms was awakened at three in the morning to be told that the Watergate Five had been arrested. Why would somebody take the trouble to notify the head of the C.I.A. — at three in the morning — about a domestic burglary? The most sensible explanation, of course, is that the arrested Watergators were active C.I.A. agents who are now protecting the Agency.

It is interesting that under the Nixon reorganization the director of the C.I.A. is also chairman of the board and coordinator of all U.S. intelligence agencies, including the Department of Defense Intelligence Agency and the ultrasecret National Security Agency. Short of the President, he is the one man in a position to tie up all of these loose ends. When Watergate broke, C.I.A. Director Richard Helms was rushed off as U.S. Ambassador to Iran. James Schlesinger was very briefly made Director, and then quickly moved up to Secretary of Defense as the Watergate scandal became the subject of national outrage. With the heat on, President Nixon named William E. Colby to be C.I.A. Director. Mr. Colby's previous job had been as head of the C.I.A.'s Directorate of Operations, where he had spent his entire career. This is the so-called "Department of Dirty Tricks," in charge of revolutionary activities and political assassination. Among the men reporting directly to him had been E. Howard Hunt.

And this raises another fascinating series of questions. Regular readers of AMERICAN OPINION will recall that in the October, 1972, issue of this magazine your reporter exposed the conspiracy to kill Governor George Wallace in Maryland on May 15, 1972. You will remember that Arthur Bremer was trained and financed to do the job by a gang of Milwaukee revolutionaries with many Communist connections. His immediate

FBI

	1 11 1				
Sinit	the following 1	n	(Type in plaintext of	code)	
	AIRTEL	*			
			(Prior	ity)	
ļ.	TO:	DIRECTOR, FBI	(149-10024)		
	FROM:	SAC, CHICAGO	(149-1060)		
	SUBJECT:	CRASH OF UNITE FLIGHT 553, BO CHICAGO, ILLIN 12/8/72 DAMV OO: CHICAGO	EING 737		
i	U.S. Dist	Enclosed for to in the Chicago grant F. BU rict Court, Chicago	Daily News, CKLEY, JR. f	iling suit in	- //(
	charges t	eath of the wif he FAA with neg Enclosed articl	e of E. HOWA ligence.	RD HUNT. Suit	
	charges t	eath of the wif he FAA with neg Enclosed articl	e of E. HOWA ligence.	RD HUNT. Suit	
	charges t	eath of the wif he FAA with neg Enclosed articl	e of E. HOWA ligence.	RD HUNT. Suit	o of
4	charges t Bureau on	eath of the wif he FAA with neg. Enclosed articlely.	e of E. HOWA	RD HUNT. Suit	of -18
K	Bureau on	eath of the wif he FAA with neg. Enclosed articlely.	REC-10	ARD HUNT. Suit	of -18

·	Sent		M	Per				
t in Charge		¢υ. S	. GOVERNMENT	PRINTING	OFFICE :	: 1969 O -	- 346-090	(11)

ENCLS. FOR BUREAU FROM SAC, CHICAGO (1)


Article appearing in CG Daily News July 9, 1974 re captioned.

CRASH OF UAL FLIGHT 553, BOEING 737, CHICAGO, ILLINOIS 12/8/72 DAMV OO: CHICAGO

BUFILE 149-10024 CG 149-1060

Via airtel dated 7/9/74





(Mount Clipping in Space Below)

Hunt estate files suit in air crash

Columnist William F. Buckley Jr. has filed suit in U.S. District Court here, asking damages for the death of the wife of convicted Watergate conspirator E. Howard Hunt.

In the suit filed Monday, Buckley said he was representing the estate of Dorothy L. Hunt, one of 45 persons killed Dec. 8, 1972, in the crash of a United Airlines jet as it approached Midway Airport.

The suit charges the Federal Aviation Administration with negligence in allowing the plane to try to land. The suit asks the court to determine proper damages.

Hunt has filed a \$2 million suit against United Airlines and Boeing Co., the plane's builder.

No date was set for hearing the new suit. The FAA denied a similar complaint on Jan. 8.

194-100 grds

(Indicate page, name of newspaper, city and state.)
• · · · · · · · · · · · · · · · · · · ·
*.
CHICAGO DAILY CHICAGO, ILLINO
- Page 8
<u></u>
Date: 7/9/74
Edition: BLUE STREAK
Author:
Editor: D. FELDMEIR
Title:
Character:
Classification:
Submitting Office: CHICAGO
Being investigated